

Operating instructions Betriebsanleitung

Miniature resistance thermometer, model TR34 (Ex i) EN

Miniatur-Widerstandsthermometer, Typ TR34 (Ex i) DE



BVS 14 ATEX E 147 X
IECEx BVS 14.0101X

70018194

GYJ15.1225X



Miniature resistance thermometer, model TR34

EN Operating instructions model TR34 (Ex i) Page 3 - 46

DE Betriebsanleitung Typ TR34 (Ex i) Seite 47 - 87

Further languages can be found at www.wika.com.

© 11/2014 WIKA Alexander Wiegand SE & Co. KG
All rights reserved. / Alle Rechte vorbehalten.
WIKA® is a registered trademark in various countries.
WIKA® ist eine geschützte Marke in verschiedenen Ländern.

Prior to starting any work, read the operating instructions!
Keep for later use!

Vor Beginn aller Arbeiten Betriebsanleitung lesen!
Zum späteren Gebrauch aufbewahren!

Contents

1. General information	5
2. Safety	7
2.1 Intended use	7
2.2 Personnel qualification	8
2.3 Additional safety instructions for instruments per ATEX	9
2.4 Special hazards	9
2.5 Labelling, safety marks	12
3. Specifications	13
4. Design and function	18
4.1 Description	18
4.2 Dimensions in mm	19
4.3 Scope of delivery	20
5. Transport, packaging and storage	21
5.1 Transport	21
5.2 Packaging	21
5.3 Storage	21
6. Commissioning, operation	22
6.1 Mounting	22
6.1.1 Tightening torques for compression fittings	23
6.1.2 Tightening torque for the M12 mating connector or the M12 adapter	23
6.2 Electrical connection	24
6.3 Behaviour of the 4 ... 20 mA electrical output signal	27
7. Configuration	28
8. Configuration software WIKAssoft-TT	29
8.1 Starting the software	29
8.2 Configuration procedure	30
8.3 Fault diagnosis	30
8.4 Measured values	30
8.5 Configure several instruments identically	30

9. Connecting PU-548 programming unit	31
10. Information on mounting and operation in hazardous areas	31
10.1 General information on explosion protection	31
10.1.1 Special conditions of use (X conditions)	34
10.1.2 Ex marking, temperature class classification and ambient temperatures	35
10.2 Overview of the temperature zones	37
10.3 Mounting examples in hazardous areas	38
11. Calculation examples for self-heating at the thermowell tip	39
11.1 Example calculation	39
12. Maintenance and cleaning	40
12.1 Maintenance	40
12.2 Cleaning	40
13. Faults	41
14. Dismounting, return and disposal	42
14.1 Dismounting	42
14.2 Return	42
14.3 Disposal	43
Appendix 1: CSA control drawing	44
Appendix 2: EU declaration of conformity	46

Declarations of conformity can be found online at www.wika.com.

1. General information

- The resistance thermometer described in the operating instructions has been designed and manufactured using state-of-the-art technology. All components are subject to stringent quality and environmental criteria during production. Our management systems are certified to ISO 9001 and ISO 14001.
- These operating instructions contain important information on handling the instrument. Working safely requires that all safety instructions and work instructions are observed.
- Observe the relevant local accident prevention regulations and general safety regulations for the instrument's range of use.
- The operating instructions are part of the product and must be kept in the immediate vicinity of the instrument and readily accessible to skilled personnel at any time.
- Skilled personnel must have carefully read and understood the operating instructions prior to beginning any work.
- The manufacturer's liability is void in the case of any damage caused by using the product contrary to its intended use, non-compliance with these operating instructions, assignment of insufficiently qualified skilled personnel or unauthorised modifications to the instrument.
- The general terms and conditions contained in the sales documentation shall apply.
- Subject to technical modifications.
- Further information:
 - Internet address: www.wika.de / www.wika.com
 - Relevant data sheet: TE 60.34
 - Application consultant: Tel.: +49 9372 132-0
Fax: +49 9372 132-406
info@wika.de

1. General information

EN



WARNING!

... indicates a potentially dangerous situation that can result in serious injury or death, if not avoided.



CAUTION!

... indicates a potentially dangerous situation that can result in light injuries or damage to equipment or the environment, if not avoided.



Information

... points out useful tips, recommendations and information for efficient and trouble-free operation.



DANGER!

... identifies hazards caused by electrical power. Should the safety instructions not be observed, there is a risk of serious or fatal injury.



WARNING!

... indicates a potentially dangerous situation in the hazardous area that can result in serious injury or death, if not avoided.



WARNING!

... indicates a potentially dangerous situation that can result in burns, caused by hot surfaces or liquids, if not avoided.

Abbreviations

- 2-wire The lead resistance is recorded as an error in the measurement.
- 3-wire With a cable length of 30 m or longer, measuring deviations can occur.
- 4-wire The lead resistance can be ignored.

2. Safety



WARNING!

Before installation, commissioning and operation, ensure that the appropriate resistance thermometer has been selected in terms of measuring range, design, specific measuring conditions and appropriate wetted parts' materials (corrosion).

Non-observance can result in serious injury and/or damage to the equipment.



Further important safety instructions can be found in the individual chapters of these operating instructions.

2.1 Intended use

The model TR34 resistance thermometer is used as a general-purpose thermometer for the measurement of temperatures from -50 ... +150 °C or -58 ... +302 °F (without neck tube) and -50 ... +250 °C or -58 ... +482 °F (with neck tube) in liquid and gaseous media. It can be used for pressures up to 140 bar with 3 mm sensor diameter and up to 270 bar with 6 mm sensor diameter, depending on the instrument version. The thermometer is designed intrinsically safe for use in hazardous areas.

The instrument has been designed and built solely for the intended use described here, and may only be used accordingly.

2. Safety

EN

The technical specifications contained in these operating instructions must be observed. Improper handling or operation of the instrument outside of its technical specifications requires the instrument to be taken out of service immediately and inspected by an authorised WIKA service engineer.

If the instrument is transported from a cold into a warm environment, the formation of condensation may result in instrument malfunction. Before putting it back into operation, wait for the instrument temperature and the room temperature to equalise.

The manufacturer shall not be liable for claims of any type based on operation contrary to the intended use.

2.2 Personnel qualification



WARNING!

Risk of injury should qualification be insufficient!

Improper handling can result in considerable injury and damage to equipment.

- The activities described in these operating instructions may only be carried out by skilled personnel who have the qualifications described below.
- Keep unqualified personnel away from hazardous areas.

Skilled electrical personnel

Skilled electrical personnel are understood to be personnel who, based on their technical training, know-how and experience as well as their knowledge of country-specific regulations, current standards and directives, are capable of carrying out work on electrical systems and independently recognising and avoiding potential hazards. The skilled electrical personnel have been specifically trained for the work environment they are working in and know the relevant standards and regulations. The skilled electrical personnel must comply with current legal accident prevention regulations.

Special operating conditions require further appropriate knowledge, e.g. of aggressive media.

2. Safety

2.3 Additional safety instructions for instruments per ATEX



WARNING!

Follow the requirements of the ATEX directive.

EN

Additionally the specifications of the respective national regulations concerning Ex usage (e.g. EN 60079-10 and EN 60079-14) apply.

Non-observance of these instructions and their contents may result in the loss of explosion protection.

- The responsibility for classification of zones lies with the plant operator and not the manufacturer/supplier of the equipment.
- The plant operator guarantees, and is solely responsible, that all thermometers in use are identifiable with respect to all safety-relevant characteristics. Damaged thermometers may not be used.
- Electrical screening may only be grounded at one end, and outside of the Ex area. Special cases are described in DIN EN 60079-14:2003.
- There must be a galvanic separation between the intrinsically safe and the non-intrinsically safe electrical circuits.

2.4 Special hazards



WARNING!

Neither repairs nor structural modifications are permitted, and any would void the guarantee and the certification.



WARNING!

Observe the information given in the applicable type examination certificate and the relevant country-specific regulations for installation and use in hazardous areas (e.g. IEC 60079-14, NEC, CEC). Non-observance can result in serious injury and/or damage to the equipment.

For additional important safety instructions for instruments with ATEX approval see chapter 2.3 "Additional safety instructions for instruments per ATEX".



WARNING!

Substitution of components may impair intrinsic safety.



WARNING!

For hazardous media such as oxygen, acetylene, flammable or toxic gases or liquids, and refrigeration plants, compressors, etc., in addition to all standard regulations, the appropriate existing codes or regulations must also be followed.



WARNING!

Protection from electrostatic discharge (ESD) required! The proper use of grounded work surfaces and personal wrist straps is required when working with exposed circuitry (printed circuit boards), in order to prevent static discharge from damaging sensitive electronic components.

To ensure safe working on the instrument, the operating company must ensure

- that suitable first-aid equipment is available and aid is provided whenever required.
- that the operating personnel are regularly instructed in all topics regarding work safety, first aid and environmental protection and know the operating instructions and in particular, the safety instructions contained therein.



DANGER!

Danger to life caused by electric current

Upon contact with live parts, there is a direct danger to life.

- Electrical instruments may only be installed and connected by skilled electrical personnel.
- Operation using a defective power supply unit (e.g. short-circuit from the mains voltage to the output voltage) can result in life-threatening voltages at the instrument!

2. Safety



WARNING!

Residual media in dismounted instruments can result in a risk to persons, the environment and equipment.
Take sufficient precautionary measures.

EN

Do not use this instrument in safety or emergency stop devices. Incorrect use of the instrument can result in injury.


Should a failure occur, aggressive media with extremely high temperature and under high pressure or vacuum may be present at the instrument.

2. Safety

2.5 Labelling, safety marks

EN

Product labels (example)



- ① Model
- ② Date of manufacture (Year-Month)
- ③ Approval-related data
- ④ Information on version (measuring element, output signal, measuring range...)
 - Thermometer with transmitter and 4 ... 20 mA output signal
 - Thermometer with direct sensor output with Pt100 and Pt1000
- ⑤ Serial number, TAG no.



Before mounting and commissioning the instrument,
ensure you read the operating instructions!

3. Specifications

EN

3. Specifications

Thermometer with transmitter and 4 ... 20 mA output signal (model TR34-x-TT)

Temperature range	Without neck tube -30 ... +150 °C (-22 ... +302 °F) With neck tube -30 ... +250 °C (-22 ... +482 °F) ¹⁾
Measuring element	Pt1000
Connection method	2-wire
Tolerance value of the measuring element	Class A (per IEC 60751)
Measuring deviation of the transmitter	±0.25 K (per IEC 60770)
Total measuring deviation in accordance with IEC 60770	Measuring deviation of the measuring element + the transmitter
Measuring span	Minimum 20 K, maximum 300 K
Basic configuration	Measuring range 0 ... 150 °C (32 ... 302 °F), other measuring ranges are adjustable
Analogue output	4 ... 20 mA, 2-wire
Linearisation	Linear to temperature per IEC 60751
Linearisation error	±0.1 % ²⁾
Switch-on delay, electrical	Max. 4 s (time before the first measured value)
Warming-up period	After approx. 4 minutes, the instrument will function to the specifications (accuracy) given in the data sheet.
Current signals for error signalling	Configurable in accordance with NAMUR NE43 downscale ≤ 3.6 mA upscale ≥ 21.0 mA
Sensor short-circuit	Not configurable, in accordance with NAMUR NE43 downscale ≤ 3.6 mA
Sensor current	< 0.3 mA (self-heating can be ignored.)
Load R_A	R _A ≤ (U _B - 10 V) / 23 mA with R _A in Ω and U _B in V
Effect of load	±0.05 % / 100 Ω
Power supply U_B	DC 10 ... 30 V

3. Specifications

Thermometer with transmitter and 4 ... 20 mA output signal (model TR34-x-TT)

EN

Max. permissible residual ripple	10 % generated by $U_B < 3\%$ ripple of the output current
Power supply input	Protected against reverse polarity
Power supply effect	$\pm 0.025\% / V$ (depending on the power supply)
Influence of the ambient temperature	0.1 % of span / $10 K T_a$
Electromagnetic compatibility (EMC) ⁴⁾	EN 61326 emission (group 1, class B) and interference immunity (industrial application) ³⁾ , configuration at 20 % of the full measuring range
Temperature units	Configurable $^{\circ}C$, $^{\circ}F$, K
Info data	TAG no., description and user message can be stored in transmitter
Configuration and calibration data	Permanently stored
Electrical connection	M12 x 1 circular connector (4-pin)

Readings in % refer to the measuring span

- 1) The temperature transmitter should therefore be protected from temperatures over $85^{\circ}C$ ($185^{\circ}F$).
- 2) $\pm 0.2\%$ for measuring ranges with a lower limit less than $0^{\circ}C$ ($32^{\circ}F$)
- 3) Use resistance thermometers with shielded cable, and ground the shield on at least one end of the lead, if the lines are longer than 30 m or leave the building. The instrument must be operated grounded.
- 4) During transient interferences (e.g. burst, surge, ESD) take into account an increased measuring deviation of up to 2 %.

3. Specifications

EN

Thermometer with direct sensor output with Pt100 (model TR34-x-Px) and Pt1000 (model TR34-x-Sx)

Temperature range	
■ Class A	Without neck tube -30 ... +150 °C (-22 ... +302 °F) With neck tube -30 ... +250 °C (-22 ... +482 °F)
■ Class B	Without neck tube -50 ... +150 °C (-58 ... +302 °F) With neck tube -50 ... +250 °C (-58 ... +482 °F)
Temperature at the connector	Max. 85 °C (185 °F)
Measuring element	■ Pt100 (measuring current: 0.1 ... 1.0 mA) ■ Pt1000 (measuring current: 0.1 ... 0.3 mA)
Connection method	■ 2-wire ■ 3-wire ■ 4-wire
Tolerance value of the measuring element per IEC 60751	■ Class A ■ Class B at 2-wire
Electrical connection	M12 x 1 circular connector (4-pin)

For detailed specifications for Pt sensors, see Technical information IN 00.17 at www.wika.com.

Case	
Material	Stainless steel
Ingress protection	■ Case with connected connector ⁵⁾ IP67 and IP69 per IEC/EN 60529, IP69K per ISO 20653 ■ Coupler connector, not connected IP67 per IEC/EN 60529
Weight in kg	approx. 0.2 ... 0.7 (depending on version)
Dimensions	see "Dimensions in mm"

5) The stated ingress protection only applies when plugged in using mating connectors that have the appropriate ingress protection.

3. Specifications

EN

Ambient conditions	
Ambient temperature range	
■ Model TR34-x-TT	-40 ... +85 °C (-40 ... +185 °F)
■ Models TR34-x-Px, TR34-x-Sx	-50 ... +85 °C (-58 ... +185 °F)
Storage temperature range	-40 ... +85 °C (-40 ... +185 °F)
Climate class per IEC 60654-1	
■ Model TR34-x-TT	Cx (-40 ... +85 °C or -40 ... +185 °F, 5 ... 95 % r. h.)
■ Models TR34-x-Px, TR34-x-Sx	Cx (-50 ... +85 °C or -58 ... +185 °F, 5 ... 95 % r. h.)
Maximum permissible humidity per IEC 60068-2-30 var. 2	r. h. 100 %, condensation allowed
Maximum operating pressure ⁶⁾⁷⁾	140 bar with 3 mm sensor diameter 270 bar with 6 mm sensor diameter
Vibration resistance per IEC 60751	10 ... 2,000 Hz, 20 g ⁶⁾
Shock resistance per IEC 60068-2-27	50 g, 6 ms, 3 axis, 3 faces, 3 times for each face
Salt fog	IEC 60068-2-11

6) Dependent on the instrument version

7) Reduced operating pressure when using a compression fitting:

Stainless steel: max. 100 bar

PTFE: max. 8 bar

Patents, property rights

M12 x 1 adapter to DIN EN 175301-803 angular connector

No. 001370985

3. Specifications

Safety-related maximum values for the current loop circuit

- Thermometer with transmitter and 4 ... 20 mA output signal (model TR34-x-TT)

EN

Parameters	Hazardous gas atmosphere	Hazardous dust atmosphere
Terminals	+ / -	+ / -
Voltage U_i	DC 30 V	DC 30 V
Current I_i	120 mA	120 mA
Power P_i	800 mW	750/650/550 mW
Effective internal capacitance C_i	29.7 nF	29.7 nF
Effective internal inductance L_i	negligible	negligible
Maximum self-heating at the sensor or thermowell tip	15 K	15 K

- Thermometer with direct sensor output with Pt100 (model TR34-x-Px) and Pt1000 (model TR34-x-Sx)

Parameters	Hazardous gas atmosphere	Hazardous dust atmosphere
Terminals	1 - 4	1 - 4
Voltage U_i	DC 30 V	DC 30 V
Current I_i	550 mA	250 mA
Power P_i	1,500 mW	750/650/550 mW
Effective internal capacitance C_i	negligible	negligible
Effective internal inductance L_i	negligible	negligible
Maximum self-heating at the sensor or thermowell tip	$(R_{th}) = 335 \text{ K/W}$	$(R_{th}) = 335 \text{ K/W}$

For further specifications see WIKA data sheet TE 60.34 and the order documentation.

4. Design and function

4. Design and function

EN

4.1 Description

The model TR34 resistance thermometer consists of a thermowell with a fixed process connection and is screwed directly into the process. It is designed to be impact and vibration resistant and all electrical components are protected against humidity (IP67 or IP69K). The vibration resistance conforms to IEC 60751 (20 g, dependent on the instrument version). The impact resistance of all versions meets the requirements of IEC 60751. Ensure that mechanical loads on the connector are minimised, especially in case of increased ambient temperatures or strong vibration loads.

The electrical connection is made with an M12 x 1 circular connector.

The following accessories may be used:

Accessories	Order no.
M12 x 1 adapter to DIN EN 175301-803-A angular connector	
■ for Pt100 and Pt1000	14061115
■ for 4 ... 20 mA	14069503
Angular connector DIN EN 175301-803-A	11427567
Sealing for angular connector, EPDM, brown	11437902
Connection cable with moulded M12 x 1 connector	
■ Cable socket straight, 4-pin, ingress protection IP67 - Temperature range -20 ... +80 °C	2 m 14086880 5 m 14086883
■ Angled socket, 4-pin, ingress protection IP67 - Temperature range -20 ... +80 °C	2 m 14086889 5 m 14086891


4. Design and function

4.2 Dimensions in mm


- Process connection with parallel threads (or without process connection)

EN


without neck tube




without process connection



with compression fitting



with neck tube



140069565.02

Legend:

A (U ₁)	Insertion length
N (M _H)	Neck length
X	Height process connection
Ød	Sensor diameter

- 1) At a process temperature of > 150 °C (302 °F), a neck length N (M_H) of 70 mm is necessary, otherwise N (M_H) selectable (55, 65 or 70 mm).


Thread	Height process connection X
G 1/2	11
G 3/8	11
G 1/4	10
M12	11
M20	11

4. Design and function


■ Process connection with tapered thread

EN


without neck tube



with compression fitting



with neck tube



140069565.02

- At a process temperature of > 150 °C (302 °F), a neck length N (M_H) of 70 mm is necessary, otherwise N (M_H) selectable (55, 65 or 70 mm).

Legend:

A (U ₂)	Insertion length
N (M _H)	Neck length
X	Height process connection
Ød	Sensor diameter

Thread	Height process connection X
1/4 NPT	15
1/2 NPT	19

4.3 Scope of delivery

Cross-check scope of delivery with delivery note.

5. Transport, packaging and storage

EN

5. Transport, packaging and storage

5.1 Transport

Check the instrument for any damage that may have been caused by transport.

Obvious damage must be reported immediately and damaged instruments must not be used.

5.2 Packaging

Do not remove packaging until just before mounting.

Keep the packaging as it will provide optimum protection during transport (e.g. change in installation site, sending for repair).

5.3 Storage

Permissible conditions at the place of storage:

- Storage temperature: -40 ... +85 °C (-40 ... +185 °F)
- Humidity: 5 ... 95 % r. h.

Avoid exposure to the following factors:

- Direct sunlight or proximity to hot objects
- Mechanical vibration, mechanical shock (putting it down hard)
- Soot, vapour, dust and corrosive gases

Store the instrument in its original packaging in a location that fulfils the conditions listed above. If the original packaging is not available, pack and store the instrument as described below:

1. Wrap the instrument in an antistatic plastic film.
2. Place the instrument, along with the shock-absorbent material, in the packaging.
3. If stored for a prolonged period of time (more than 30 days), place a bag containing a desiccant inside the packaging.



WARNING!

Before storing the instrument (following operation), remove any residual media. This is of particular importance if the medium is hazardous to health, e.g. caustic, toxic, carcinogenic, radioactive, etc.

6. Commissioning, operation

EN



WARNING!

Avoid putting any mechanical loading on the electrical connections and on the cases. Connections must only be opened once the instrument has been depressurised and has cooled down.

Maximum permissible temperatures:

- At case with transmitter: 85 °C (185 °F)
- Class A:
 - Without neck tube -30 ... +150 °C (-22 ... +302 °F)
 - With neck tube -30 ... +250 °C (-22 ... +482 °F)
- Class B:
 - Without neck tube -50 ... +150 °C (-58 ... +302 °F)
 - With neck tube -50 ... +250 °C (-58 ... +482 °F)

6.1 Mounting

These resistance thermometers are designed for screw-fitting directly into the process. The insertion length, along with the flow velocity and viscosity of the process media, may reduce the max. loading on the thermowell.

The case must be grounded against electromagnetic fields and electrostatic discharge. It is not necessary to connect the case separately to the equipotential bonding system, provided that it has a fixed and secure contact to the metallic vessel, its components or pipes, and that these are connected to the equipotential bonding system.

When there is a non-metallic contact with the vessel, or with its structural components or piping, all projecting, electrically conducting thermometer components in the hazardous area must be provided with equipotential bonding.




WARNING!

Neither repairs nor structural modifications are permitted, and any would void the guarantee and the certification.

6. Commissioning, operation

EN

Installation examples



For information on tapped holes, refer to DIN 3852 or for NPT threads to ANSI B 1.20.

6.1.1 Tightening torques for compression fittings

Sealing	Rotation	Max. pressure in bar
Stainless steel ferrule	1 1/4 ... 1 1/2	100
Stainless steel compression ring	1 1/4 ... 1 1/2	100
PTFE ferrule	1 1/4 ... 1 1/2	8

6.1.2 Tightening torque for the M12 mating connector or the M12 adapter

Select a tightening torque of 0.6 Nm.


6. Commissioning, operation

EN

6.2 Electrical connection


The electrical connection is made via a M12 x 1 (4-pin) circular connector.

- Output signal Pt100 and Pt1000 (standard)



Alternative pin assignments possible.
For further information see order documentation.


Accessories: M12 x 1 Pt adapter to DIN EN 175301-803 angular connector



6. Commissioning, operation

EN


■ Output signal 4 ... 20 mA (standard)



Pin	Signal	Description
1	L+	10 ... 30 V
2	VQ	not connected
3	L-	0 V
4	C	not connected

Alternative pin assignments possible.
For further information see order documentation.

Accessories: M12 x 1 transmitter adapter to DIN EN 175301-803 angular connector



Pin assignment angular connector

Pin	Signal	Description
1	L+	10 ... 30 V
2	L-	0 V
3	VQ	not connected
4	C	not connected



DANGER!

Danger to life caused by electric current

Upon contact with live parts, there is a direct danger to life.

- The instrument may only be installed and mounted by skilled personnel.
- Operation using a defective power supply unit (e.g. short-circuit from the mains voltage to the output voltage) can result in life-threatening voltages at the instrument!
- Carry out mounting work only with power disconnected.


This is protection class 3 equipment for connection at low voltages, which are separated from the power supply or voltages of greater than AC 50 V or DC 120 V. Preferably, a connection to an SELV or PELV circuit is recommended; alternatively protective measures from HD 60346-4-41 (DIN VDE 0100-410).

Alternatively for North America

The connection can be made in line with "Class 2 Circuits" or "Class 2 Power Units" in accordance with CEC (Canadian Electrical Code) or NEC (National Electrical Code).

Load diagram

The permissible load depends on the loop supply voltage. For communication with the instrument with programming unit PU-548, a max. load of 350Ω is admissible.



6. Commissioning, operation

EN

6.3 Behaviour of the 4 ... 20 mA electrical output signal

■ Sensor break and short circuit

Sensor break or short circuit are signalled after positive detection (after approx. 1 second). If this fault condition has been caused by a malfunction, then a relevant measurement signal must exist for approx. 1 second in order to return to measuring mode. From the time of the error detection up to the error signalling, the last relevant measured value will be delivered on the current loop.


Therefore, in the event of a “true” sensor break or short-circuit, this is also signalled permanently. In the event of a “false” sensor break or short-circuit, the transmitter has the possibility of reverting to measuring mode.

■ Medium temperature outside the span

If the media temperature exceeds that configured within the transmitter, the transmitter will operate in a linear fashion within the following limits: 3.8 mA (MRS); 20.5 mA (MRE). If these limits are exceeded, then an error will be signalled.

■ Hysteresis on return to the measuring span

After the linear error limits have been exceeded, on return to the measuring span, a hysteresis of 0.1 mA must be passed. This hysteresis prevents the transmitter from jumping back and forth between error and measuring mode.



7. Configuration

7. Configuration

EN

Configuration is carried out using a USB interface with a PC via the model PU-548 programming unit (accessories, order no. 14231581). The connection with the thermometer is made via the appropriate adapter cable. (Accessories: M12 x 1 circular connector, order no. 14003193)

Measuring range, damping, error signalling, TAG no. and other parameters can be adjusted (see configuration software).



- Easy to use
- LED status display
- Compact design
- No further voltage supply is needed for either the programming unit or for the transmitter

(replaces programming unit model PU-448)

The measuring range is configurable between -50 ... +250 °C (-58 ... +482 °F). The configuration software checks the desired measuring range and will only accept permissible values. Intermediate values are configurable - the smallest increment is 0.1 °C or 0.1 °F. The thermometers are delivered configured to customer specifications within the configurable limits.

Please note:

The measuring range of the thermometer is limited by the application range of the measuring element, not by the setting range of the transmitter.

Maximum permissible temperatures:

- At case with transmitter: 85 °C (185 °F)
- Class A:
 - Without neck tube -30 ... +150 °C (-22 ... +302 °F)
 - With neck tube -30 ... +250 °C (-22 ... +482 °F)
- Class B:
 - Without neck tube -50 ... +150 °C (-58 ... +302 °F)
 - With neck tube -50 ... +250 °C (-58 ... +482 °F)

8. Configuration software WIKAsoft-TT

EN

8. Configuration software WIKAsoft-TT

For installation please follow the instructions of the installation routine.

8.1 Starting the software

Start the configuration software by double-clicking on the WIKAsoft-TT icon.


After starting the software, the language can be changed, via the selection of the appropriate country's flag.

The selection of the COM port is made automatically.

After the connection of a transmitter (using the PU-548), on pressing the "Start" button, the configuration interface is loaded.



The configuration interface can only be loaded when an instrument is connected.



8. Configuration software WIKAsoft-TT

EN

8.2 Configuration procedure

Steps 1 and 2 are carried out automatically when starting the software.

1. "Loading the instrument data"
2. "Loading configuration"
3. [optional] Cancel write protection ("key" symbol at the bottom right)
4. Change the required parameters
→ Sensor/Measuring range/Error signalling etc.
5. "Save to the instrument"
6. [optional] Activate write protection
7. [optional] Print configuration protocol
8. [optional] Test: "Loading configuration" → checking the configuration

8.3 Fault diagnosis

Here, in the event of an "error detected by the transmitter", the error message is displayed.

Examples: Sensor break, permitted highest temperature exceeded, etc.
In normal operation, "No fault - No maintenance requirement" is displayed here.

8.4 Measured values


Line recorder - Here the measured value progression is represented in the format of a chart recorder with a constant sampling rate in a defined time interval (180 seconds) and a variable temperature axis.

The display purely serves as a functional check and for information.
An export of the data is not possible.

8.5 Configure several instruments identically

- First instrument
 1. "Loading configuration"
 2. [optional] Cancel write protection ("key" symbol at the bottom right)
 3. Change the required parameters
 4. "Save to the instrument"
 5. [optional] Activate write protection
- All subsequent instruments
 1. "Loading the instrument data"
 2. [optional] Cancel write protection
 3. [optional] Change the required parameters, e. g. TAG number
 4. "Save to the instrument"
 5. [optional] Activate write protection

9. Connecting PU-548 programming unit



(predecessor, programming unit model PU-448, also compatible)

10. Information on mounting and operation in hazardous areas

10.1 General information on explosion protection



The requirements of the ATEX directive must be followed. Additionally the specifications of the respective national regulations concerning Ex usage (e.g. IEC/EN 60079-10 and IEC/EN 60079-14) apply.

10. Information on mounting and operation in ...

EN

- For the installation of the thermometers, only components (e.g. cables, cable glands, etc.) permitted for "intrinsic safety" may be used.
- For grounding the conductive screen, follow the specifications of IEC/EN 60079-14.
- The temperature resistance of the connecting cable must match the permissible operating temperature of the cases.
For ambient temperatures above 60 °C, heat-resistant connecting cable must be used (see table in chapter 4 "Design and function").
- Mounting within metallic enclosures:
The case must be grounded against electromagnetic fields and electrostatic discharge. It does not have to be connected separately to the equipotential bonding system. It is sufficient if the metallic thermowell has a solid and secured contact with the metallic vessel or its structural components or pipelines, so long as these components are connected to the equipotential bonding system.
- Mounting within non-metallic enclosures:
 - Ground the cable shield at one end, preferably in the safe, and so non-Ex, area (EN 60079-14) . For instruments with cable output, the shield is connected to the case. The simultaneous connection of the case and the cable shield to ground is only permitted if any accidental energisation between the shield connection (e.g. at the power supply) and the case can be excluded (see EN 60079-14).
 - Power the resistance thermometer via an intrinsically safe current circuit (Ex ia).
 - Both the effective internal capacitance and inductance must be considered
 - Fine-gauge wires with bare ends must be finished with end splices (cable preparation).
 - With cables for use in zone 1 and 2, the test voltage between conductor/ground, conductor/screen, screen/ground must be > AC 500 V.
- Neither repairs nor structural modifications are permitted, and any would void the guarantee and the respective certification.
- The manufacturer shall not be responsible for constructional modifications after delivery of the instruments.

10. Information on mounting and operation in ...

EN

- A) The responsibility for classification of zones lies with the plant operator and not the manufacturer/supplier of the equipment.
- B) The plant operator guarantees, and is solely responsible, that all thermometers in use are identifiable with respect to all safety-relevant characteristics. Damaged thermometers may not be used. Repairs may only be carried out by authorised and qualified personnel. Repairs may only be completed using original spare parts from the original supplier; otherwise the requirements of the approval are not fulfilled.
The manufacturer shall not be responsible for constructional modifications after delivery of the instruments.
- C) If a component of electrical equipment, on which the explosion protection depends, is repaired, then the electrical equipment may only be put back into use, after an authorised expert has stated that it corresponds to the fundamental characteristics of the requirements for explosion protection. In addition this expert must provide a certificate for this and provide the equipment with a test mark.
- D) Item C) shall not apply if the component was repaired by the manufacturer in accordance with the requirements and regulations.
- E) When ordering spare parts, the parts that are to be replaced must be specified exactly:
- Ignition protection type (here Ex i)
 - Approval no.
 - Order no.
 - Manufacturing no.
 - Order item

10.1.1 Special conditions of use (X conditions)

1. Thermal backflow from the process, that exceeds the permissible ambient temperature of the transmitter or the cases, must not be allowed to occur and must be prevented by the installation of suitable heat insulation or a neck tube of suitable length.
2. The wall thickness is greater than 0.2 mm and less than 1 mm. Thus the instruments must not be subjected to ambient stresses that may have an adverse effect on the partition wall. Alternatively, a thermowell of suitable minimum wall thickness may be used.
3. When using a thermowell/neck tube, the overall instrument must be designed such that it allows installation in a way that results in a sufficiently tight clearance (IP67) or a flameproof gap (IEC/EN 60079-1) towards the less hazardous area.
4. The ambient temperature range (T_a) for variants with optional connection cable with moulded M12 x 1 connector is limited to -20 ... +80 °C.
5. The ambient temperature range (T_a) for variants with optional EN 175301 M12 adapters is limited to -40 ... +85 °C.

10. Information on mounting and operation in ...

EN

10.1.2 Ex marking, temperature class classification and ambient temperatures

For applications without transmitters (models TR34-x-Px and TR34-x-Sx) that require Group II instruments (potentially explosive gas atmospheres), the following temperature class classification and ambient temperature ranges apply:

Table 1

Marking	Temperature class	Ambient temperature range (T_a)	Max. surface temperature (T_{max}) at the sensor or thermowell tip
II 1G Ex ia IIC T1 - T6 Ga	T6	-50 ... +80 °C	T_M (medium temperature) + self-heating
	T5	-50 ... +85 °C	
II 1/2G Ex ia IIC T1 - T6 Ga/Gb	T4	-50 ... +85 °C	Pay attention to the specific conditions for safe use (see chapter 10.1.1 "Special conditions of use (X conditions)").
	T3	-50 ... +85 °C	
II 2G Ex ia IIC T1 - T6 Gb	T2	-50 ... +85 °C	
	T1	-50 ... +85 °C	

For applications requiring instruments of equipment Group II (potentially explosive dust atmospheres), the following surface temperatures and ambient temperature ranges apply:

Table 2

Marking	Power P_i	Ambient temperature range (T_a)	Max. surface temperature (T_{max}) at the sensor or thermowell tip
II 1D Ex ia IIIC T135 °C Da	750 mW	-50 ... +40 °C	T_M (medium temperature) + self-heating
	650 mW	-50 ... +70 °C	
II 2D Ex ia IIIC T135 °C Db	550 mW	-50 ... +85 °C	Pay attention to the specific conditions for safe use (see chapter 10.1.1 "Special conditions of use (X conditions)").

10. Information on mounting and operation in ...

For applications with transmitters (TR34-x-TT) that require Group II instruments (potentially explosive gas atmospheres), the following temperature class classification and ambient temperature ranges apply:

EN

Table 3

Hazardous gas atmosphere	Temperature class	Ambient temperature range (T_a)	Max. surface temperature (T_{max}) at the sensor or thermowell tip
II 1G Ex ia IIC T1 - T6 Ga	T6	-40 ... +45 °C	T_M (medium temperature) + self-heating (15 K)
	T5	-40 ... +60 °C	
II 1/2G Ex ia IIC T1 - T6 Ga/Gb	T4	-40 ... +85 °C	Pay attention to the specific conditions for safe use (see chapter 10.1.1 "Special conditions of use (X conditions)").
	T3	-40 ... +85 °C	
II 2G Ex ia IIC T1 - T6 Gb	T2	-40 ... +85 °C	
	T1	-40 ... +85 °C	

For applications requiring instruments of equipment Group II (potentially explosive dust atmospheres), the following surface temperatures and ambient temperature ranges apply:

Table 4

Hazardous dust atmosphere	Power P_I	Ambient temperature range (T_a)	Max. surface temperature (T_{max}) at the sensor or thermowell tip
II 1D Ex ia IIIC T135 °C Da	750 mW	-40 ... +40 °C	T_M (medium temperature) + self-heating (15 K)
	650 mW	-40 ... +70 °C	
II 1/2D Ex ia IIIC T135 °C Da/Db	550 mW	-40 ... +85 °C	Pay attention to the specific conditions for safe use (see chapter 10.1.1 "Special conditions of use (X conditions)").


10. Information on mounting and operation in ...

EN

For applications that require EPL Gb or Db, the instruments designated as "ia" can also be used in type "ib" measuring circuits, with the same connection parameters.

Thus the entire measuring circuit (including the sensor circuit) is an "ib" current circuit. Instruments that have been operated in a power supply circuit of type "ib" cannot be re-used in a power supply circuit of type "ia".


10.2 Overview of the temperature zones



10. Information on mounting and operation in ...

EN

10.3 Mounting examples in hazardous areas



11. Calculation examples for self-heating at the thermowell tip

11.1 Example calculation

Use at the partition to zone 0

The maximum possible temperature, T_{\max} , at the Ø 6 mm thermowell tip with transmitter is being sought.

T_{\max} is obtained by adding the medium temperature and the self-heating. The self-heating depends on the supplied power P_0 as well as the thermal resistance R_{th} and is 15 K.

Example

Diameter: 6 mm

Medium temperature: $T_M = 150 \text{ }^{\circ}\text{C}$

Temperature class T3 (200 °C) must not be exceeded

Self-heating: 15 K

$$T_{\max} = T_M + \text{self-heating: } 150 \text{ }^{\circ}\text{C} + 15 \text{ K} = 165 \text{ }^{\circ}\text{C}$$

As safety margin for type-examined instruments (for T6 to T3), an additional 5 °C must be subtracted from the 200 °C; hence 195 °C would be permissible. This means that in this case temperature class T3 is not exceeded.

Additional information:

Temperature class for T3 = 200 °C

Safety margin for type-tested instruments (for T6 to T3)¹⁾ = 5 K

Safety margin for type-tested instruments (for T2 to T1)¹⁾ = 10 K

1) IEC/EN 60079-0: 2012 Ch. 26.5.1

12. Maintenance and cleaning

12. Maintenance and cleaning

EN

12.1 Maintenance

The resistance thermometers described here require absolutely no maintenance and contain no components which could be repaired or replaced.

12.2 Cleaning



CAUTION!

- Before cleaning the instrument, disconnect the electrical connections.
- Clean the instrument with a moist cloth. This applies in particular to thermometers with a case made of plastic and cable sensors with plastic-insulated connecting cable, to ensure that any risk of electrostatic discharge is avoided.
- Electrical connections must not come into contact with moisture.
- Wash or clean the dismounted instrument before returning it, in order to protect persons and the environment from exposure to residual media.
- Residual media in dismounted instruments can result in a risk to persons, the environment and equipment. Take sufficient precautionary measures.



For information on returning the instrument, see chapter 14.2 "Return".

13. Faults

EN

13. Faults

Faults	Causes	Measures
No signal/line break	Mechanical load too high or overtemperature	Replace the sensor with a suitable version
Erroneous measured values	Sensor drift caused by overtemperature	Replace the sensor with a suitable version
	Sensor drift caused by chemical attack	Analyse the medium
Erroneous measured values (too low)	Entry of moisture into cable	Use the appropriate IP protection
Erroneous measured values and response times too long	Wrong mounting geometry, for example mounting depth too deep or heat dissipation too high	The temperature-sensitive area of the sensor must be inside the medium, and surface measurements must be ungrounded
	Deposits on the thermowell	Remove deposits
Temporary or intermittent interruptions of the measured value signal	Cable break in connection cable or loose contact caused by mechanical overload	Replace the sensor or use thicker conductor cross-section
Corrosion	Composition of the medium not as expected or modified	Analyse the medium
Signal interference	Stray currents caused by electric fields or earth loops	Use of screened connecting cables, increase in the distance to motors and power lines
	Earth loops	Elimination of potentials, use of galvanically isolated transmitter supply isolators or transmitters



CAUTION!

If faults cannot be eliminated by means of the measures listed above, the instrument must be shut down immediately, and it must be ensured that signal is no longer present, and it must be prevented from being inadvertently put back into service. In this case, contact the manufacturer.
If a return is needed, follow the instructions given in chapter 14.2 "Return".

14. Dismounting, return and disposal



WARNING!

Residual media in dismounted instruments can result in a risk to persons, the environment and equipment.
Take sufficient precautionary measures.

14.1 Dismounting



WARNING!

Risk of burns!

Let the instrument cool down sufficiently before dismounting it!
During dismounting there is a risk of dangerously hot media escaping.

Only disconnect the resistance thermometer once the system has been depressurised!

14.2 Return



WARNING!

Strictly observe the following when shipping the instrument:

All instruments delivered to WIKA must be free from any kind of hazardous substances (acids, bases, solutions, etc.).

14. Dismounting, return and disposal

EN

When returning the instrument, use the original packaging or a suitable transport packaging.

To avoid damage:

1. Wrap the instrument in an antistatic plastic film.
2. Place the instrument, along with the shock-absorbent material, in the packaging.
Place shock-absorbent material evenly on all sides of the transport packaging.
3. If possible, place a bag containing a desiccant inside the packaging.
4. Label the shipment as carriage of a highly sensitive measuring instrument.



Information on returns can be found under the heading "Service" on our local website.

14.3 Disposal


Incorrect disposal can put the environment at risk.

Dispose of instrument components and packaging materials in an environmentally compatible way and in accordance with the country-specific waste disposal regulations.

Appendix 1: CSA control drawing

EN

Intrinsically safe installation



ENTITY APPROVED / CERTIFIED INTRINSICALLY SAFE

Notes:

- The intrinsic safety entity concept allows the interconnection of two intrinsically safe devices with entity parameters not specifically examined in combination as a system when:
 $V_{max} \leq V_{oc}$, $V_I \leq V_{oc}$, $I_{max} \leq I_{sc}$, $I_T \leq I_{sc}$, $P_{max} \leq P_{sc}$, $L_A \geq L_{sc}$, $C_A \geq C_{sc}$, $L_A \geq L_{sc} + L_{cable}$.
- Associated apparatus must be accordingly certified.
- Control equipment connected to the associated apparatus must not use or generate more than 250 Vrms or Vdc.
- Installation should be in accordance with the Canadian Electrical Code (CEC) for Canada or with ANSI/ISA RP12.06.01 "Installation of Intrinsically safe systems for hazardous classified locations" and the National Electrical Code (NEC) sections 500 and 505 for USA.
- The configuration of associated apparatus must be under entity control.
- Associated apparatus manufacturer's installation drawing must be followed when installing this equipment.
- No revision to this drawing without prior approval.


Nonincendive field wiring installation

NON HAZARDOUS LOCATION

HAZARDOUS LOCATION :
 Class I, Division 2, Groups A, B, C, D
 Class I, Zone 2
 Class II or III, Division 2, Groups E, F, G
 Class II or III, Zone 22

NIFW parameters TR21-*W*, TR31-*W*, TR34-W*

Intrinsic safety barrier not required. V_{max} or $U_{I} \leq DC 30 V$



Notes:

1. Nonincendive field wiring enables interconnection of nonincendive field wiring apparatus with associated nonincendive field wiring apparatus or associated intrinsically safe apparatus not specifically examined in combination as a system under one of the following conditions:
 - a) Current Controlled

Normal operating current controlled or limited by the nonincendive field wiring apparatus. Unlike the requirements for intrinsically safe apparatus, max. or is of the nonincendive field wiring apparatus need not be greater than the isc. If isc or is of the associated nonincendive field wiring apparatus need

- V_{max} or $I_{is} = V_{dc}$, $I_{is} \geq Ci \cdot Cdc$, $Li \cdot Ldc$
- b) Not current controlled

Normal operating voltage or current not controlled or limited by the nonincendive field wiring apparatus

- V_{max} or $I_{is} = V_{dc}$, $V_{dc} \geq Li \cdot Vdc$ or $I_{is} \leq Ci \cdot Idc$
- 2. Associated apparatus manufacturer's installation drawing must be followed when installing this equipment.

3. No revision to this drawing without prior approval.

Appendix 2: EU declaration of conformity

EN



EU-Konformitätserklärung EU Declaration of Conformity

Dokument Nr.: 14113906.04
Document No.:

Wir erklären in alleiniger Verantwortung, dass die mit CE gekennzeichneten Produkte
We declare under our sole responsibility that the CE marked products

Typbezeichnung: TR34
Type Designation:

Beschreibung: Miniaturl-Widerstandsthermometer, Typ TR34 Ex i
Description: Miniature resistance thermometer, model TR34 Ex i

gemäß gültigem Datenblatt:
according to the valid data sheet:

die wesentlichen Schutzanforderungen der folgenden Richtlinien erfüllen:
comply with the essential protection requirements of the directives:

Harmonisierte Normen:
Harmonized standards:

2011/65/EU Gefährliche Stoffe (RoHS)
Hazardous substances (RoHS) EN 50581:2012

2014/30/EU Elektromagnetische Verträglichkeit (EMV)
Electromagnetic Compatibility (EMC) EN 61326-1:2013

2014/34/EU Explosionsschutz (ATEX) (1)
Explosion protection (ATEX) (1) EN 61326-2-3:2013

II 1G Ex ia IIC T1 - T6 Ga
II 1/2G Ex ia IIC T1 - T6 Ga/Gb

(1) EN 60079-0:2012+A11:2013

II 2G Ex ia IIC T1 - T6 Gb

EN 60079-11:2012

II 1/2G Ex ib IIC T1 - T6 Ga/Gb

EN 60079-26:2015

II 1D Ex ia IIIC T135 °C Da

II 1/2D Ex ia IIIC T135 °C Da/Dc

II 2D Ex ia IIIC T135 °C Db

II 2D Ex ib IIIC T135 °C Db

II 1/2D Ex ib IIIC T135 °C Da/Dc

II 1/2D Ex ia IIIC T135 °C Da

II 1/2D Ex ib IIIC T135 °C Da

(1) Modelle ohne eingebaute Transmitter oder Anzeigen erfüllen die Stoffschränkungen nach 2011/65/EU, dürfen aber nicht die CE-Kennzeichnung tragen, da es keine Geräte nach Definition 2011/65/EU sind.

Models without built-in transmitters or displays meet the substance restrictions of 2011/65/EU, but must not bear the CE marking, as they are no devices as defined in 2011/65/EU.

(2) Nur mit Ausgangssignal 4 ... 20 mA
With analogue output signal 4 ... 20 mA only

Unterzeichnet für und im Namen von / Signed for and on behalf of

WIKA Alexander Wiegand SE & Co. KG

Klingenberg, 2018-04-26

Stefan Heidinger, Vice President
Electrical Temperature Measurement

WIKA Alexander Wiegand SE & Co. KG
Alexander-Wiegand-Straße 30
63911 Klingenberg
Germany

Tel. +49 9372 132-0
Fax +49 9372 132-406
E-Mail info@wika.de
www.wika.de

Kommendesgericht: Sitz Klingenberg –
Amtsgericht Aschaffenburg IURA 1819
Komplementär: WIKA Verwaltungs SE & Co. KG –
Sitz Klingenberg – Amtsgericht Aschaffenburg
HRA 4685

Unterschriftenbereich:
WIKA International SE - Sitz Klingenberg -
Amtsgericht Aschaffenburg HRB 10505
Vorstand: Alexander Wiegand
Vorsitzender des Aufsichtsrates: Dr. Max Egli
1BAR-XXXX

Franz-Josef Vogel, Executive Vice President
Process Instrumentation

Inhalt

1. Allgemeines	49
2. Sicherheit	51
2.1 Bestimmungsgemäße Verwendung	51
2.2 Personalqualifikation	52
2.3 Zusätzliche Sicherheitshinweise für Geräte nach ATEX	53
2.4 Besondere Gefahren	53
2.5 Beschilderung, Sicherheitskennzeichnungen	56
3. Technische Daten	57
4. Aufbau und Funktion	62
4.1 Beschreibung	62
4.2 Abmessungen in mm	63
4.3 Lieferumfang	64
5. Transport, Verpackung und Lagerung	65
5.1 Transport	65
5.2 Verpackung	65
5.3 Lagerung	65
6. Inbetriebnahme, Betrieb	66
6.1 Montage	66
6.1.1 Anzugsdrehmomente für Klemmverschraubungen	67
6.1.2 Anzugsdrehmoment für den M12-Gegenstecker oder den M12-Adapter	67
6.2 Elektrischer Anschluss	68
6.3 Verhalten des elektrischen Ausgangssignals 4 ... 20 mA	71
7. Konfiguration	72
8. Konfigurationssoftware WIKAsoft-TT	73
8.1 Starten der Software	73
8.2 Ablauf Konfiguration	74
8.3 Fehlerdiagnose	74
8.4 Messwerte	74
8.5 Mehrere Geräte identisch konfigurieren	74

9. Programmiereinheit PU-548 anschließen	75
10. Hinweise zu Montage und Betrieb im explosionsgefährdeten Bereich	75
10.1 Allgemeine Hinweise zum Explosionsschutz	75
10.1.1 Besondere Bedingungen für die Verwendung (X-Conditions)	78
10.1.2 Ex-Kennzeichnung, Temperaturklasseneinteilung und Umgebungstemperaturen	79
10.2 Übersicht der Temperaturzonen	81
10.3 Montagebeispiele im explosionsgefährdeten Bereich	82
11. Berechnungsbeispiele für die Eigenerwärmung an der Schutzrohrspitze	83
11.1 Beispieldberechnung	83
12. Wartung und Reinigung	84
12.1 Wartung	84
12.2 Reinigung	84
13. Störungen	85
14. Demontage, Rücksendung und Entsorgung	86
14.1 Demontage	86
14.2 Rücksendung	86
14.3 Entsorgung	87
Anlage 1: CSA control drawing	44
Anlage 2: EU-Konformitätserklärung	46

Konformitätserklärungen finden Sie online unter www.wika.de.

1. Allgemeines

- Das in der Betriebsanleitung beschriebene Widerstandsthermometer wird nach dem aktuellen Stand der Technik konstruiert und gefertigt. Alle Komponenten unterliegen während der Fertigung strengen Qualitäts- und Umweltkriterien. Unsere Managementsysteme sind nach ISO 9001 und ISO 14001 zertifiziert.
- Diese Betriebsanleitung gibt wichtige Hinweise zum Umgang mit dem Gerät. Voraussetzung für sicheres Arbeiten ist die Einhaltung aller angegebenen Sicherheitshinweise und Handlungsanweisungen.
- Die für den Einsatzbereich des Gerätes geltenden örtlichen Unfallverhütungsvorschriften und allgemeinen Sicherheitsbestimmungen einhalten.
- Die Betriebsanleitung ist Produktbestandteil und muss in unmittelbarer Nähe des Gerätes für das Fachpersonal jederzeit zugänglich aufbewahrt werden.
- Das Fachpersonal muss die Betriebsanleitung vor Beginn aller Arbeiten sorgfältig durchgelesen und verstanden haben.
- Die Haftung des Herstellers erlischt bei Schäden durch bestimmungswidrige Verwendung, Nichtbeachten dieser Betriebsanleitung, Einsatz ungenügend qualifizierten Fachpersonals sowie eigenmächtiger Veränderung am Gerät.
- Es gelten die allgemeinen Geschäftsbedingungen in den Verkaufsunterlagen.
- Technische Änderungen vorbehalten.
- Weitere Informationen:
 - Internet-Adresse: www.wika.de / www.wika.com
 - zugehöriges Datenblatt: TE 60.34
 - Anwendungsberater: Tel.: +49 9372 132-0
Fax: +49 9372 132-406
info@wika.de

1. Allgemeines

Symbolerklärung



WARNUNG!

... weist auf eine möglicherweise gefährliche Situation hin, die zum Tod oder zu schweren Verletzungen führen kann, wenn sie nicht gemieden wird.

DE



VORSICHT!

... weist auf eine möglicherweise gefährliche Situation hin, die zu geringfügigen oder leichten Verletzungen bzw. Sach- und Umweltschäden führen kann, wenn sie nicht gemieden wird.



Information

... hebt nützliche Tipps und Empfehlungen sowie Informationen für einen effizienten und störungsfreien Betrieb hervor.



GEFAHR!

... kennzeichnet Gefährdungen durch elektrischen Strom. Bei Nichtbeachtung der Sicherheitshinweise besteht die Gefahr schwerer oder tödlicher Verletzungen.



WARNUNG!

... weist auf eine möglicherweise gefährliche Situation im explosionsgefährdeten Bereich hin, die zum Tod oder zu schweren Verletzungen führen kann, wenn sie nicht gemieden wird.



WARNUNG!

... weist auf eine möglicherweise gefährliche Situation hin, die durch heiße Oberflächen oder Flüssigkeiten zu Verbrennungen führen kann, wenn sie nicht gemieden wird.

Abkürzungen

- 2-Leiter Der Leitungswiderstand geht als Fehler in die Messung ein.
- 3-Leiter Ab einer Kabellänge von 30 m können Messabweichungen auftreten.
- 4-Leiter Der Leitungswiderstand kann vernachlässigt werden.

2. Sicherheit



WARNUNG!

Vor Montage, Inbetriebnahme und Betrieb sicherstellen, dass das richtige Widerstandsthermometer hinsichtlich Messbereich, Ausführung, spezifischen Messbedingungen und geeignetem messstoffberührtem Werkstoff (Korrosion) ausgewählt wurde.

Bei Nichtbeachten können schwere Körperverletzungen und/oder Sachschäden auftreten.



Weitere wichtige Sicherheitshinweise befinden sich in den einzelnen Kapiteln dieser Betriebsanleitung.

2.1 Bestimmungsgemäße Verwendung

Das Widerstandsthermometer Typ TR34 wird als universelles Thermometer zum Messen von Temperaturen von -50 ... +150 °C bzw. -58 ... +302 °F (ohne Halsrohr) und -50 ... +250 °C bzw. -58 ... +482 °F (mit Halsrohr) in flüssigen und gasförmigen Medien verwendet. Es ist einsetzbar für Drücke bis 140 bar bei Sensordurchmesser 3 mm und bis 270 bar bei Sensordurchmesser 6 mm, abhängig von der Geräteausführung. Das Thermometer ist eigensicher für den Einsatz in explosionsgefährdeten Bereichen ausgeführt.

Das Gerät ist ausschließlich für den hier beschriebenen bestimmungsgemäßen Verwendungszweck konzipiert und konstruiert und darf nur dementsprechend verwendet werden.

2. Sicherheit

Die technischen Spezifikationen in dieser Betriebsanleitung sind einzuhalten. Eine unsachgemäße Handhabung oder ein Betreiben des Gerätes außerhalb der technischen Spezifikationen macht die sofortige Stilllegung und Überprüfung durch einen autorisierten WIKA-Servicemitarbeiter erforderlich.

DE

Wird das Gerät von einer kalten in eine warme Umgebung transportiert, so kann durch Kondensatbildung eine Störung der Gerätefunktion eintreten. Vor einer erneuten Inbetriebnahme die Angleichung der Gerätetemperatur an die Raumtemperatur abwarten.
Ansprüche jeglicher Art aufgrund von nicht bestimmungsgemäßer Verwendung sind ausgeschlossen.

2.2 Personalqualifikation



WARNUNG!

Verletzungsgefahr bei unzureichender Qualifikation!

Unsachgemäßer Umgang kann zu erheblichen Personen- und Sachschäden führen.

- Die in dieser Betriebsanleitung beschriebenen Tätigkeiten nur durch Fachpersonal nachfolgend beschriebener Qualifikation durchführen lassen.
- Unqualifiziertes Personal von den Gefahrenbereichen fernhalten.

Elektrofachpersonal

Das Elektrofachpersonal ist aufgrund seiner fachlichen Ausbildung, Kenntnisse und Erfahrungen sowie Kenntnis der landesspezifischen Vorschriften, geltenden Normen und Richtlinien in der Lage, Arbeiten an elektrischen Anlagen auszuführen und mögliche Gefahren selbstständig zu erkennen und zu vermeiden. Das Elektrofachpersonal ist speziell für das Arbeitsumfeld, in dem es tätig ist, ausgebildet und kennt die relevanten Normen und Bestimmungen. Das Elektrofachpersonal muss die Bestimmungen der geltenden gesetzlichen Vorschriften zur Unfallverhütung erfüllen.

Spezielle Einsatzbedingungen verlangen weiteres entsprechendes Wissen, z. B. über aggressive Medien.

2. Sicherheit

2.3 Zusätzliche Sicherheitshinweise für Geräte nach ATEX



WARNUNG!

Die Anforderungen der ATEX-Richtlinie beachten.
Zusätzlich gelten die Angaben der jeweiligen Landesvorschriften bezüglich Ex-Einsatz (z. B. EN 60079-10 und EN 60079-14).

DE

Die Nichtbeachtung dieser Inhalte und Anweisungen kann zum Verlust des Explosionsschutzes führen.

- Die Verantwortung über die Zoneneinteilung unterliegt dem Anlagenbetreiber und nicht dem Hersteller/Lieferanten der Betriebsmittel.
- Der Betreiber der Anlage stellt in eigener Verantwortung sicher, dass vollständige und im Einsatz befindliche Thermometer bezüglich aller sicherheitsrelevanten Merkmale identifizierbar sind. Beschädigte Thermometer dürfen nicht verwendet werden.
- Leitende Schirme dürfen nur einseitig und außerhalb des Ex-Bereiches geerdet werden. Sonderfälle sind in DIN EN 60079-14:2003 beschrieben.
- Es muss eine galvanische Trennung zwischen dem eigensicheren und dem nichteigensicheren Stromkreis bestehen.

2.4 Besondere Gefahren



WARNUNG!

Reparaturen sowie bauliche Veränderungen sind nicht zulässig und führen zur Erlösung der Garantie und der Zulassungen.



WARNUNG!

Die Angaben der geltenden Baumusterprüfbescheinigung sowie die jeweiligen landesspezifischen Vorschriften zur Installation und Einsatz in explosionsgefährdeten Bereichen (z. B. IEC 60079-14, NEC, CEC) enthalten. Bei Nichtbeachten können schwere Körperverletzungen und/oder Sachschäden auftreten.

Weitere wichtige Sicherheitshinweise für Geräte mit ATEX-Zulassung siehe Kapitel 2.3 "Zusätzliche Sicherheitshinweise für Geräte nach ATEX".



WARNUNG!

Der Austausch von Bauteilen kann die Eigensicherheit beeinträchtigen.



WARNUNG!

Bei gefährlichen Messstoffen wie z. B. Sauerstoff, Acetylen, brennbaren oder giftigen Stoffen, sowie bei Kälteanlagen, Kompressoren etc. müssen über die gesamten allgemeinen Regeln hinaus die einschlägigen Vorschriften beachtet werden.



WARNUNG!

Schutz vor elektrostatischer Entladung (ESD) erforderlich! Die ordnungsgemäße Verwendung geerdeter Arbeitsflächen und persönlicher Armbänder ist bei Arbeiten mit offenen Schaltkreisen (Leiterplatten) erforderlich, um die Beschädigung empfindlicher elektronischer Bauteile durch elektrostatische Entladung zu vermeiden.

Für ein sicheres Arbeiten am Gerät muss der Betreiber sicherstellen,

- dass eine entsprechende Erste-Hilfe-Ausrüstung vorhanden ist und bei Bedarf jederzeit Hilfe zur Stelle ist.
- dass das Bedienpersonal regelmäßig in allen zutreffenden Fragen von Arbeitssicherheit, Erste-Hilfe und Umweltschutz unterwiesen wird, sowie die Betriebsanleitung und insbesondere die darin enthaltenen Sicherheitshinweise kennt.



GEFAHR!

Lebensgefahr durch elektrischen Strom

Bei Berührung mit spannungsführenden Teilen besteht unmittelbare Lebensgefahr.

- Einbau und Montage des elektrischen Gerätes dürfen nur durch das Elektrofachpersonal erfolgen.
- Bei Betrieb mit einem defekten Netzgerät (z. B. Kurzschluss von Netzzspannung zur Ausgangsspannung) können am Gerät lebensgefährliche Spannungen auftreten!

2. Sicherheit



WARNUNG!

Messstoffreste in ausgebauten Geräten können zur Gefährdung von Personen, Umwelt und Einrichtung führen.
Ausreichende Vorsichtsmaßnahmen ergreifen.

Dieses Gerät nicht in Sicherheits- oder in Not-Aus-Einrichtungen benutzen. Fehlerhafte Anwendungen des Gerätes können zu Verletzungen führen.


DE

Am Gerät können im Fehlerfall aggressive Medien mit extremer Temperatur und unter hohem Druck oder Vakuum anliegen.

2. Sicherheit

2.5 Beschilderung, Sicherheitskennzeichnungen

Typenschilder (Beispiel)



- ① Typ
- ② Herstellungsdatum (Jahr-Monat)
- ③ Zulassungsrelevante Daten
- ④ Angaben zur Ausführung (Messelement, Ausgangssignal, Messbereich...)
 - Thermometer mit Messumformer und Ausgangssignal 4 ... 20 mA
 - Thermometer mit direktem Sensorausgang mit Pt100 und Pt1000
- ⑤ Seriennummer, TAG-Nummer



Vor Montage und Inbetriebnahme des Gerätes
unbedingt die Betriebsanleitung lesen!

3. Technische Daten

3. Technische Daten

Thermometer mit Messumformer und Ausgangssignal 4 ... 20 mA (Typ TR34-x-TT)

DE

Temperaturbereich	Ohne Halsrohr -30 ... +150 °C (-22 ... +302 °F) Mit Halsrohr -30 ... +250 °C (-22 ... +482 °F) ¹⁾
Messelement	Pt1000
Schaltungsart	2-Leiter
Grenzabweichung des Messelements	Klasse A (nach IEC 60751)
Messabweichung des Messumformers	±0,25 K (nach IEC 60770)
Gesamtmessabweichung nach IEC 60770	Messabweichung des Messelements + des Messumformers
Messspanne	Minimal 20 K, maximal 300 K
Grundkonfiguration	Messbereich 0 ... 150 °C (32 ... 302 °F), andere Messbereiche sind einstellbar
Analogausgang	4 ... 20 mA, 2-Draht
Linearisierung	Temperaturlinear nach IEC 60751
Linearitätsfehler	±0,1 % ²⁾
Einschaltverzögerung, elektrisch	Max. 4 s (Zeit bis zum ersten Messwert)
Anwärmzeit	Nach ca. 4 Minuten werden die im Datenblatt angegebenen technischen Daten (Genauigkeit) erreicht.
Stromwerte für Fehler-signalisierung	Konfigurierbar nach NAMUR NE43 zusteuern $\leq 3,6 \text{ mA}$ aufsteuern $\geq 21,0 \text{ mA}$
Fühlerkurzschluss	Nicht konfigurierbar, nach NAMUR NE43 zusteuern $\leq 3,6 \text{ mA}$
Sensorstrom	$< 0,3 \text{ mA}$ (Eigenerwärmung kann vernachlässigt werden.)
Bürde R_A	$R_A \leq (U_B - 10 \text{ V}) / 23 \text{ mA}$ mit R_A in Ω und U_B in V
Bürdeneinfluss	±0,05 % / 100 Ω
Hilfsenergie U_B	DC 10 ... 30 V

3. Technische Daten

Thermometer mit Messumformer und Ausgangssignal 4 ... 20 mA (Typ TR34-x-TT)

DE

Max. zulässige Restwelligkeit	10 % von U_B erzeugt < 3 % Welligkeit des Ausgangstromes
Hilfsenergееingang	Geschützt gegen Verpolung
Hilfsenergееinfluss	$\pm 0,025 \% / V$ (abhängig von der Hilfsenergie)
Einfluss der Umgebungstemperatur	0,1 % der Spanne / $10 K T_a$
Elektromagnetische Verträglichkeit (EMV)⁴⁾	EN 61326 Emission (Gruppe 1, Klasse B) und Störfestigkeit (industrieller Bereich) ³⁾ , Konfiguration bei 20 % des vollen Messbereichs
Temperatureinheiten	Konfigurierbar °C, °F, K
Info-Daten	TAG-Nr., Beschreibung und Anwendernachricht im Transmitter speicherbar
Konfigurations- und Kalibrierungsdaten	Dauerhaft gespeichert
Elektrischer Anschluss	M12 x 1-Rundstecker (4-polig)

Angaben in % beziehen sich auf die Messspanne

- 1) Den Temperatur-Transmitter dabei vor Temperaturen über 85 °C (185 °F) schützen.
- 2) $\pm 0,2 \%$ bei Messbereichsanfang kleiner 0 °C (32 °F)
- 3) Widerstandsthermometer mit geschirmter Leitung betreiben und den Schirm auf mindestens einer Leitungsseite erden, wenn die Leitungen länger als 30 m sind oder das Gebäude verlassen. Das Gerät geerdet betreiben.
- 4) Während transienten Störbeeinflussungen (z. B. Burst, Surge, ESD) eine erhöhte Messabweichung von bis zu 2 % berücksichtigen.

3. Technische Daten

DE

Thermometer mit direktem Sensorausgang mit Pt100 (Typ TR34-x-Px) und Pt1000 (Typ TR34-x-Sx)

Temperaturbereich	■ Klasse A Ohne Halsrohr -30 ... +150 °C (-22 ... +302 °F) Mit Halsrohr -30 ... +250 °C (-22 ... +482 °F)
Temperatur am Stecker	Max. 85 °C (185 °F)
Messelement	■ Pt100 (Messstrom: 0,1 ... 1,0 mA) ■ Pt1000 (Messstrom: 0,1 ... 0,3 mA)
Schaltungsart	■ 2-Leiter ■ 3-Leiter ■ 4-Leiter
Grenzabweichung des Messelements nach IEC 60751	■ Klasse A ■ Klasse B bei 2-Leiter
Elektrischer Anschluss	M12 x 1-Rundstecker (4-polig)

Detaillierte Angaben zu Pt-Sensoren siehe Technische Information IN 00.17 unter www.wika.de.

Gehäuse

Material	CrNi-Stahl
Schutzart	■ Gehäuse mit gestecktem Stecker ⁵⁾ IP67 und IP69 nach IEC/EN 60529, IP69K nach ISO 20653 ■ Anschlussstecker ungesteckt IP67 nach IEC/EN 60529
Gewicht in kg	ca. 0,2 ... 0,7 (je nach Ausführung)
Maße	siehe „Abmessungen in mm“

5) Die angegebenen Schutzarten gelten nur im gesteckten Zustand mit Leitungssteckern entsprechender Schutzart.

3. Technische Daten

DE

Umgebungsbedingungen	
Umgebungstemperaturbereich	
■ Typ TR34-x-TT	-40 ... +85 °C (-40 ... +185 °F)
■ Typen TR34-x-Px, TR34-x-Sx	-50 ... +85 °C (-58 ... +185 °F)
Lagertemperaturbereich	-40 ... +85 °C (-40 ... +185 °F)
Klimaklasse nach IEC 60654-1	
■ Typ TR34-x-TT	Cx (-40 ... +85 °C bzw. -40 ... +185 °F, 5 ... 95 % r. F.)
■ Typen TR34-x-Px, TR34-x-Sx	Cx (-50 ... +85 °C bzw. -58 ... +185 °F, 5 ... 95 % r. F.)
Maximal zulässige Feuchte nach IEC 60068-2-30 Var. 2	r. F. 100 %, Betauung zulässig
Maximaler Betriebsdruck^{6) 7)}	140 bar bei Sensordurchmesser 3 mm 270 bar bei Sensordurchmesser 6 mm
Vibrationsbeständigkeit nach IEC 60751	10 ... 2.000 Hz, 20 g ⁶⁾
Schockfestigkeit nach IEC 60068-2-27	50 g, 6 ms, 3 Achsen, 3 Richtungen, 3-mal je Richtung
Salznebel	IEC 60068-2-11

6) Abhängig von der Geräteausführung

7) Reduzierter Betriebsdruck bei Verwendung einer Klemmverschraubung:

CrNi-Stahl: max. 100 bar

PTFE: max. 8 bar

Patente, Schutzrechte

Adapter M12 x 1 zu Winkelstecker
DIN EN 175301-803

Nr. 001370985

3. Technische Daten

Sicherheitstechnische Höchstwerte für den Stromschleifenkreis

- Thermometer mit Messumformer und Ausgangssignal 4 ... 20 mA (Typ TR34-x-TT)

Kenngrößen	Explosionsgefährdete Gasatmosphäre	Explosionsgefährdete Staubatmosphäre
Klemmen	+ / -	+ / -
Spannung U_i	DC 30 V	DC 30 V
Stromstärke I_i	120 mA	120 mA
Leistung P_i	800 mW	750/650/550 mW
Innere wirksame Kapazität C_i	29,7 nF	29,7 nF
Innere wirksame Induktivität L_i	vernachlässigbar	vernachlässigbar
Maximale Eigenerwärmung an der Fühler- oder Schutzrohrspitze	15 K	15 K

- Thermometer mit direktem Sensorausgang mit Pt100 (Typ TR34-x-Px) und Pt1000 (Typ TR34-x-Sx)

Kenngrößen	Explosionsgefährdete Gasatmosphäre	Explosionsgefährdete Staubatmosphäre
Klemmen	1 - 4	1 - 4
Spannung U_i	DC 30 V	DC 30 V
Stromstärke I_i	550 mA	250 mA
Leistung P_i	1.500 mW	750/650/550 mW
Innere wirksame Kapazität C_i	vernachlässigbar	vernachlässigbar
Innere wirksame Induktivität L_i	vernachlässigbar	vernachlässigbar
Maximale Eigenerwärmung an der Fühler- oder Schutzrohrspitze	$(R_{th}) = 335 \text{ K/W}$	$(R_{th}) = 335 \text{ K/W}$

Weitere technische Daten siehe WIKA-Datenblatt TE 60.34 und Bestellunterlagen.

DE

4. Aufbau und Funktion

4. Aufbau und Funktion

4.1 Beschreibung

Das Widerstandsthermometer Typ TR34 besteht aus einem Schutzrohr mit festem Prozessanschluss und wird direkt in den Prozess eingeschraubt. Es ist stoß- und vibrationsfest aufgebaut und alle elektrischen Bauteile sind gegen Feuchtigkeit geschützt (IP67 bzw. IP69K). Die Vibrationsfestigkeit entspricht der IEC 60751 (20 g, abhängig von der Geräteausführung). Die Stoßfestigkeit entspricht für alle Versionen den Anforderungen der IEC 60751. Insbesondere bei erhöhten Umgebungstemperaturen oder starker Vibrationsbelastung darauf achten, dass mechanische Belastungen am Stecker minimiert werden.
Die elektrische Kontaktierung erfolgt mit Rundstecker M12 x 1.


Folgendes Zubehör darf verwendet werden:

Zubehör	Bestell-Nr.
Adapter M12 x 1 zu Winkelstecker DIN EN 175301-803-A	
■ für Pt100 und Pt1000	14061115
■ für 4 ... 20 mA	14069503
Winkelstecker DIN EN 175301-803-A	11427567
Dichtung für Winkelstecker, EPDM, braun	11437902
Anschlusskabel mit geformtem Stecker M12 x 1	
■ Kabdose gerade, 4-polig, Schutzart IP67 - Temperaturbereich -20 ... +80 °C	2 m 14086880 5 m 14086883
■ Winkeldose, 4-polig, Schutzart IP67 - Temperaturbereich -20 ... +80 °C	2 m 14086889 5 m 14086891

4. Aufbau und Funktion

4.2 Abmessungen in mm

- Prozessanschluss mit zylindrischem Gewinde (bzw. ohne Prozessanschluss)




Gewinde	Höhe Prozessanschluss X
G 1/2	11
G 3/8	11
G 1/4	10
M12	11
M20	11

4. Aufbau und Funktion


■ Prozessanschluss mit kegeligem Gewinde

DE


ohne Halsrohr



mit Klemmverschraubung



mit Halsrohr



140069565.02

- Bei Prozesstemperatur > 150 °C (302 °F) ist eine Halslänge N (M_H) von 70 mm erforderlich, ansonsten N (M_H) wählbar (55, 65 oder 70 mm).

Legende:
A (U_2) Einbaulänge
N (M_H) Halslänge
X Höhe Prozessanschluss
Ød Sensordurchmesser

Gewinde	Höhe Prozessanschluss X
1/4 NPT	15
1/2 NPT	19

4.3 Lieferumfang

Lieferumfang mit dem Lieferschein abgleichen.

5. Transport, Verpackung und Lagerung

5.1 Transport

Gerät auf eventuell vorhandene Transportschäden untersuchen.

Offensichtliche Schäden unverzüglich mitteilen und beschädigte Geräte nicht verwenden.

DE

5.2 Verpackung

Verpackung erst unmittelbar vor der Montage entfernen.

Die Verpackung aufbewahren, denn diese bietet bei einem Transport einen optimalen Schutz (z. B. wechselnder Einbauort, Reparatursendung).

5.3 Lagerung

Zulässige Bedingungen am Lagerort:

- Lagertemperatur: -40 ... +85 °C (-40 ... +185 °F)
- Feuchtigkeit: 5 ... 95 % r. F.

Folgende Einflüsse vermeiden:

- Direktes Sonnenlicht oder Nähe zu heißen Gegenständen
- Mechanische Vibration, mechanischer Schock (hartes Aufstellen)
- Ruß, Dampf, Staub und korrosive Gase

Das Gerät in der Originalverpackung an einem Ort, der die oben gelisteten Bedingungen erfüllt, lagern. Wenn die Originalverpackung nicht vorhanden ist, dann das Gerät wie folgt verpacken und lagern:

1. Das Gerät in eine antistatische Plastikfolie einhüllen.
2. Das Gerät mit dem Dämmmaterial in der Verpackung platzieren.
3. Bei längerer Einlagerung (mehr als 30 Tage) einen Beutel mit Trocknungsmittel der Verpackung beilegen.



WARNUNG!

Vor der Einlagerung des Gerätes (nach Betrieb) alle anhaftenden Messstoffreste entfernen. Dies ist besonders wichtig, wenn der Messstoff gesundheitsgefährdend ist, wie z. B. ätzend, giftig, krebserregend, radioaktiv, usw.

6. Inbetriebnahme, Betrieb

6. Inbetriebnahme, Betrieb



WARNUNG!

Mechanische Belastungen der elektrischen Anschlüsse und der Gehäuse vermeiden. Alle Anschlüsse nur im drucklosen und abgekühlten Zustand öffnen.

DE

Maximal zulässige Temperaturen:

- Am Gehäuse mit Transmitter: 85 °C (185 °F)
- Klasse A:
 - Ohne Halsrohr -30 ... +150 °C (-22 ... +302 °F)
 - Mit Halsrohr -30 ... +250 °C (-22 ... +482 °F)
- Klasse B:
 - Ohne Halsrohr -50 ... +150 °C (-58 ... +302 °F)
 - Mit Halsrohr -50 ... +250 °C (-58 ... +482 °F)

6.1 Montage

Diese Widerstandsthermometer sind vorgesehen zum direkten Einschrauben in den Prozess. Einbaulänge sowie Strömungsgeschwindigkeit und Viskosität des Prozessmediums können sich reduzierend auf die max. Schutzrohrbelastung auswirken.

Das Gehäuse muss gegen elektromagnetische Felder und elektrostatische Aufladungen geerdet werden. Es muss nicht gesondert an das Potentialausgleichssystem angeschlossen werden, wenn es festen und gesicherten metallischen Kontakt mit dem Behälter oder dessen Konstruktionsteilen oder Rohrleitungen hat, sofern diese mit dem Potentialausgleichssystem verbunden sind.

Bei einem nichtmetallischen Kontakt mit dem Behälter oder dessen Konstruktionsteilen bzw. Rohrleitungen müssen alle in den explosionsgefährdeten Bereich ragende, elektrisch leitende Thermometerkomponenten mit einem Potentialausgleich versehen werden.




WARNUNG!

Reparaturen sowie bauliche Veränderungen sind nicht zulässig und führen zur Erlösung der Garantie und der Zulassungen.

6. Inbetriebnahme, Betrieb

Einbaubeispiele



Angaben zu den Einschraublöchern der DIN 3852 bzw. für NPT-Gewinde der ANSI B 1.20 entnehmen.

6.1.1 Anzugsdrehmomente für Klemmverschraubungen

Dichtung	Umdrehungen	Max. Druck in bar
Klemmring CrNi-Stahl	1 ¼ ... 1 ½	100
Schneidring CrNi-Stahl	1 ¼ ... 1 ½	100
Klemmring PTFE	1 ¼ ... 1 ½	8

6.1.2 Anzugsdrehmoment für den M12-Gegenstecker oder den M12-Adapter

Anzugsdrehmoment von 0,6 Nm wählen.


6. Inbetriebnahme, Betrieb

6.2 Elektrischer Anschluss

Der elektrische Anschluss erfolgt über den Rundstecker M12 x 1 (4-polig).


- Ausgangssignal Pt100 und Pt1000 (Standard)

DE




Alternative Anschlussbelegungen möglich.
Weitere Informationen siehe Bestellunterlagen.

Zubehör: Pt-Adapter M12 x 1 zu Winkelstecker DIN EN 175301-803



6. Inbetriebnahme, Betrieb

- Ausgangssignal 4 ... 20 mA (Standard)




DE

Pin	Signal	Beschreibung
1	L+	10 ... 30 V
2	VQ	nicht angeschlossen
3	L-	0V
4	C	nicht angeschlossen

Alternative Anschlussbelegungen möglich.
Weitere Informationen siehe Bestellunterlagen.

Zubehör: Transmitter-Adapter M12 x 1 zu Winkelstecker DIN EN 175301-803



Anschlussbelegung Winkelstecker

Pin	Signal	Beschreibung
1	L+	10 ... 30 V
2	L-	0 V
3	VQ	nicht angeschlossen
4	C	nicht angeschlossen



GEFAHR!

Lebensgefahr durch elektrischen Strom

Bei Berührung mit spannungsführenden Teilen besteht unmittelbare Lebensgefahr.

- Einbau und Montage des Gerätes dürfen nur durch Fachpersonal erfolgen.
- Bei Betrieb mit einem defekten Netzgerät (z. B. Kurzschluss von Netzspannung zur Ausgangsspannung) können am Gerät lebensgefährliche Spannungen auftreten!
- Montagen im spannungslosen Zustand durchführen.

DE


Dies ist ein Betriebsmittel der Schutzklasse 3 zum Anschluss an Kleinspannungen, die von der Netzspannung oder Spannung größer AC 50 V bzw. DC 120 V getrennt sind. Zu bevorzugen ist ein Anschluss an SELV- oder PELV-Stromkreise; alternativ ist eine Schutzmaßnahme aus HD 60346-4-41 (DIN VDE 0100-410) zu empfehlen.

Alternativ für Nordamerika

Der Anschluss kann auch an „Class 2 Circuits“ oder „Class 2 Power Units“ gemäß CEC (Canadian Electrical Code) oder NEC (National Electrical Code) erfolgen.

Bürdendiagramm

Die zulässige Bürde hängt von der Spannung der Schleifenversorgung ab. Bei Kommunikation mit dem Gerät, mit Programmiereinheit PU-548, ist eine Bürde von maximal 350Ω zulässig.



6.3 Verhalten des elektrischen Ausgangssignals 4 ... 20 mA

■ Fühlerbruch und Kurzschluss

Fühlerbruch bzw. Kurzschluss werden nach sicherem Erkennen (nach ca. 1 Sekunde) signalisiert. Wird dieser Fehler jedoch durch eine Fehlfunktion verursacht, so muss für ebenfalls ca. 1 Sekunde ein relevantes Messsignal anliegen um wieder in den Messmodus zu gelangen. Ab dem Zeitpunkt der Erkennung bis zur Fehlersignalisierung wird der letzte relevante Messwert auf der Stromschleife ausgegeben.


Somit wird im Falle eines „wahren“ Fühlerbruches bzw. Kurzschlusses dieser auch dauerhaft signalisiert. Im Falle eines „falschen“ Fühlerbruches bzw. Kurzschlusses hat der Transmitter die Möglichkeit, wieder in den Messbetrieb zu gelangen.

■ Medientemperatur außerhalb der Spanne

Bei einer Überschreitung der im Transmitter konfigurierten Medientemperatur läuft der Transmitter noch linear in folgende Grenzen: 3,8 mA (MBA); 20,5 mA (MBE). Werden diese überschritten, so wird ein Fehler signalisiert.

■ Hysterese beim Rücklauf in die Messspanne

Nach einer Überschreitung der linearen Fehlergrenzen muss beim Rücklauf in die Messspanne eine Hysterese von 0,1 mA überschritten werden. Diese Hysterese verhindert, dass der Transmitter am Rande der Fehlergrenzen zwischen Fehler und Messmodus hin- und herspringt.



7. Konfiguration

Das Konfigurieren erfolgt über die USB-Schnittstelle eines PC's via Programmiereinheit Typ PU-548 (Zubehör, Bestell-Nr. 14231581). Mittels passendem Adapterkabel wird die Verbindung zum Thermometer hergestellt. (Zubehör: Rundstecker M12 x 1, Bestell-Nr. 14003193)

DE

Einstellbar sind Messbereich, Dämpfung, Fehlersignalisierung, TAG-Nr. sowie weitere Parameter, siehe Konfigurationssoftware.



- Einfache Bedienung
- LED-Statusanzeige
- Kompakte Bauform
- Keine zusätzliche Spannungsversorgung weder für die Programmiereinheit noch für den Transmitter notwendig

(ersetzt Programmiereinheit Typ PU-448)

Der Messbereich ist konfigurierbar zwischen -50 ... +250 °C (-58 ... +482 °F). Die Konfigurationssoftware überprüft den gewünschten Messbereich und akzeptiert nur zulässige Werte. Zwischenwerte sind konfigurierbar, die kleinste Schrittweite ist 0,1 °C oder 0,1 °F. Ausgeliefert werden die Thermometer konfiguriert nach Kundenvorgabe im Rahmen der Konfigurationsmöglichkeiten.

Bitte beachten:

Der Messbereich des Thermometers wird begrenzt durch den Anwendungsbereich des Messelementes, nicht durch den Einstellbereich des Transmitters.

Maximal zulässige Temperaturen:

- Am Gehäuse mit Transmitter: 85 °C (185 °F)
- Klasse A:
 - Ohne Halsrohr -30 ... +150 °C (-22 ... +302 °F)
 - Mit Halsrohr -30 ... +250 °C (-22 ... +482 °F)
- Klasse B:
 - Ohne Halsrohr -50 ... +150 °C (-58 ... +302 °F)
 - Mit Halsrohr -50 ... +250 °C (-58 ... +482 °F)

8. Konfigurationssoftware WIKAsoft-TT

8. Konfigurationssoftware WIKAsoft-TT

Zur Installation den Anweisungen der Installationsroutine folgen.

8.1 Starten der Software

Die Kofigurationssoftware mit einem Doppelklick auf das WIKAsoft-TT Icon starten.

DE

Nach dem Starten der Software kann die Sprache über Auswahl der entsprechenden Länderflagge geändert werden.


Die Auswahl des COM-Ports erfolgt automatisch.



Nach dem Anschluss eines Transmitters (mit PU-548) kann durch Aktivieren des Start-Buttons die Konfigurationsoberfläche geladen werden.



Die Konfigurationsoberfläche kann nur mit einem angeschlossenen Gerät geladen werden.



8.2 Ablauf Konfiguration

Die Schritte 1 und 2 erfolgen beim Start der Software automatisch.

1. „Gerätedaten laden“
2. „Konfiguration laden“
3. [optional] Schreibschutz aufheben (Schlosssymbol unten rechts)
4. Ändern der gewünschten Parameter
→ Sensor/Messbereich/Fehlersignalisierung etc.
5. „In das Gerät speichern“
6. [optional] Schreibschutz aktivieren
7. [optional] Konfigurationsprotokoll ausdrucken
8. [optional] Test: „Konfiguration laden“ → Konfiguration überprüfen

8.3 Fehlerdiagnose

Hier wird im Fall eines „vom Transmitter detektierten Fehlers“ die Fehlermeldung angezeigt.

Beispiele: Sensorbruch, Zulässige Höchsttemperatur überschritten etc.
Im Betriebsfall wird hier „Kein Fehler - Kein Wartungsbedarf“ ausgegeben.

8.4 Messwerte

Linienschreiber – Hier wird der Messwertverlauf mit einer konstanten Abtastrate in einem definierten Zeitraster (180 Sekunden) und einer variablen Temperaturachse in Form eines Linienschreiber dargestellt.
Die Anzeige dient rein zur Funktionsprüfung und zur Information.


Ein Export der Daten ist nicht möglich.

8.5 Mehrere Geräte identisch konfigurieren

- Erstes Gerät
 1. „Konfiguration laden“
 2. [optional] Schreibschutz aufheben (Schlosssymbol unten rechts)
 3. Ändern der gewünschten Parameter
 4. „In das Gerät speichern“
 5. [optional] Schreibschutz aktivieren
- Alle folgenden Geräte
 1. „Gerätedaten laden“
 2. [optional] Schreibschutz aufheben
 3. [optional] Ändern der gewünschten Parameter, z. B. TAG-Nummer
 4. „In das Gerät speichern“
 5. [optional] Schreibschutz aktivieren

9. Programmiereinheit PU-548 anschließen

Anschluss PU-548 ↔ Adapterkabel mit Anschluss M12



(Vorgängermodell, Programmiereinheit Typ PU-448, ebenfalls kompatibel)

10. Hinweise zu Montage und Betrieb im explosionsgefährdeten Bereich

10.1 Allgemeine Hinweise zum Explosionsschutz



Die Anforderungen der ATEX-Richtlinie müssen beachtet werden. Zusätzlich gelten die Angaben der jeweiligen Landesvorschriften bezüglich Ex-Einsatz (z. B. IEC/EN 60079-10 und IEC/EN 60079-14).

10. Hinweise zu Montage und Betrieb im Ex-Bereich

- Bei der Installation der Thermometer, sind nur Bauteile (z. B. Leitungen, Kabelverschraubungen etc.) zulässig, die für Eigensicherheit geeignet sind.
- Für die Erdung leitender Schirme die Bedingungen nach IEC/EN 60079-14 beachten.
- Die Temperaturbeständigkeit der Anschlussleitung muss dem zulässigen Betriebstemperaturbereich der Gehäuse entsprechen.
Bei Umgebungstemperaturen über 60 °C sind wärmebeständige Anschlussleitungen zu verwenden (siehe Tabelle in Kapitel 4 „Aufbau und Funktion“).
- Montage in metallischen Behälter:
Das Gehäuse muss gegen elektromagnetische Felder und elektrostatische Aufladung geerdet werden. Es muss nicht gesondert an das Potentialausgleichssystem angeschlossen werden. Es ist ausreichend, wenn das metallische Schutzrohr festen und gesicherten Kontakt mit dem metallischen Behälter oder dessen Konstruktionsteilen oder Rohrleitungen hat, insofern diese Bauteile mit einem Potentialausgleichssystem verbunden sind.
- Montage in nichtmetallische Behälter:
- Den Kabelschirm einseitig und bevorzugt im sicheren, also Nicht-Ex-Bereich (EN 60079-14) erden. Bei Geräten mit Kabelausgang ist der Schirm mit dem Gehäuse verbunden. Der gleichzeitige Anschluss von Gehäuse und Kabelschirm an Erde ist nur dann zulässig, wenn eine Potentialverschleppung zwischen Schirmanschluss (z. B. am Speisegerät) und Gehäuse ausgeschlossen werden kann (siehe EN 60079-14).
- Das Widerstandsthermometer aus einem eigensicheren Stromkreis (Ex ia) versorgen.
- Die innere wirksame Kapazität und Induktivität beachten.
- Feindrahtige Leiterenden mit Aderendhülsen (Kabelkonfektionierung) versehen.
- Bei Kabeln für den Einsatz in Zone 1 und 2 muss die Prüfspannung Leiter/Erde, Leiter/Schirm, Schirm/Erde > 500 V Wechselspannung betragen.
- Reparaturen sowie bauliche Veränderungen sind nicht zulässig und führen zur Erlösung der Garantie und der jeweiligen Zulassung.
- Bauliche Veränderungen nach Auslieferung der Geräte obliegen nicht der Verantwortung des Herstellers.

10. Hinweise zu Montage und Betrieb im Ex-Bereich

DE

- A) Die Verantwortung über die Zoneneinteilung unterliegt dem Anlagenbetreiber und nicht dem Hersteller/Lieferanten der Betriebsmittel.
- B) Der Betreiber der Anlage stellt in eigener Verantwortung sicher, dass vollständige und im Einsatz befindliche Thermometer bezüglich aller sicherheitsrelevanten Merkmale identifizierbar sind. Beschädigte Thermometer dürfen nicht verwendet werden. Instandsetzungen (Reparaturen) dürfen nur von dafür autorisierten Personen durchgeführt werden. Reparaturen dürfen nur mit Originalersatzteilen des Ursprungslieferanten durchgeführt werden, da ansonsten die Anforderungen der Zulassung nicht erfüllt sind.
Bauliche Veränderungen nach Auslieferung der Geräte obliegen nicht in der Verantwortung des Herstellers.
- C) Ist eine Komponente eines elektrischen Betriebsmittels, von dem der Explosionsschutz abhängt, instandgesetzt worden, so darf das elektrische Betriebsmittel erst wieder in Betrieb genommen werden, nachdem der Sachverständige festgestellt hat, dass es in den für den Explosionsschutz wesentlichen Merkmalen den Anforderungen entspricht. Außerdem muss der Sachverständige hierfür eine Bescheinigung erstellen und das Betriebsmittel mit einem Prüfzeichen versehen.
- D) Punkt C) gilt dann nicht, wenn die Komponente durch den Hersteller entsprechend den Anforderungen und Bestimmungen instandgesetzt wurde.
- E) Bei Ersatzteilbestellung muss eine genaue Angabe über die Vorführung erfolgen:
- Zündschutzart (hier Ex i)
 - Zulassungs-Nr.
 - Auftrags-Nr.
 - Fertigungs-Nr.
 - Auftragsposition

10. Hinweise zu Montage und Betrieb im Ex-Bereich

10.1.1 Besondere Bedingungen für die Verwendung (X-Conditions)

1. Ein Wärmerückfluss aus dem Prozess welcher die zulässige Umgebungstemperatur des Transmitters oder des Gehäuses überschreitet, ist nicht zulässig und durch geeignete Wärmeisolierung oder ein entsprechend langes Halsrohr zu verhindern.
- DE**
2. Die Wandstärke ist größer als 0,2 mm und kleiner als 1 mm. Die Geräte daher keinen Umgebungsbeanspruchungen aussetzen, die die Trennwand nachteilig beeinträchtigen können. Alternativ kann ein Schutzrohr mit entsprechender Mindestwandstärke eingesetzt werden.
3. Bei Verwendung eines Schutzrohrs/Halsrohrs muss das Gesamtgerät so konstruiert sein, dass ein Einbau in einer Art möglich ist, die zu einem genügend dichten Spalt (IP67) oder einem flammendurchschlagsicheren Spalt (IEC/EN 60079-1) hin zum weniger gefährdeten Bereich führt.
4. Die Umgebungstemperaturbereich (T_a) für Varianten mit optionalem Anschlusskabel mit geformtem Stecker M12 x 1 ist begrenzt auf -20 ... +80 °C.
5. Die Umgebungstemperaturbereich (T_a) für Varianten mit optionalem Adapter M12 - EN 175301 ist begrenzt auf -40 ... +85 °C.

10. Hinweise zu Montage und Betrieb im Ex-Bereich

10.1.2 Ex-Kennzeichnung, Temperaturklasseneinteilung und Umgebungstemperaturen

Für Anwendungen ohne Transmitter (Typen TR34-x-Px, TR34-x-Sx), die Geräte der Gerätekategorie II (explosionsfähige Gasatmosphären) erfordern, gelten folgende Temperaturklasseneinteilung und Umgebungstemperaturbereiche:

DE

Tabelle 1

Kennzeichnung	Temperaturklasse	Umgebungstemperaturbereich (T_a)	Max. Oberflächentemperatur (T_{max}) an der Fühler- oder Schutzrohrspitze
II 1 G Ex ia IIC T1 - T6 Ga	T6	-50 ... +80 °C	T_M (Mediumstemperatur) + Eigenerwärmung
	T5	-50 ... +85 °C	
II 1/2 G Ex ia IIC T1 - T6 Ga/Gb	T4	-50 ... +85 °C	Besondere Bedingungen für die sichere Anwendung berücksichtigen (siehe Kapitel 10.1.1 „Besondere Bedingungen für die Verwendung (X-Conditions)“).
	T3	-50 ... +85 °C	
II 2 G Ex ia IIC T1 - T6 Gb	T2	-50 ... +85 °C	
	T1	-50 ... +85 °C	

Für Anwendungen, die Geräte der Gerätekategorie II (explosionsfähige Staubatmosphären) erfordern, gelten folgende Oberflächentemperaturen und Umgebungstemperaturbereiche:

Tabelle 2

Kennzeichnung	Leistung P_i	Umgebungstemperaturbereich (T_a)	Max. Oberflächentemperatur (T_{max}) an der Fühler- oder Schutzrohrspitze
II 1 D Ex ia IIIC T135 °C Da	750 mW	-50 ... +40 °C	T_M (Mediumstemperatur) + Eigenerwärmung
	650 mW	-50 ... +70 °C	
II 2 D Ex ia IIIC T135 °C Db	550 mW	-50 ... +85 °C	Besondere Bedingungen für die sichere Anwendung berücksichtigen (siehe Kapitel 10.1.1 „Besondere Bedingungen für die Verwendung (X-Conditions)“).

10. Hinweise zu Montage und Betrieb im Ex-Bereich

Für Anwendungen mit Transmitter (TR34-x-TT), die Geräte der Gerätekategorie II (explosionsfähige Gasatmosphären) erfordern, gelten die folgenden Temperaturklasseneinteilung und Umgebungstemperaturbereiche:

Tabelle 3

Explosionsgefährdete Gasatmosphäre	Temperaturklasse	Umgebungstemperaturbereich (T_a)	Max. Oberflächentemperatur (T_{max}) an der Fühler- oder Schutzrohrspitze
II 1 G Ex ia IIC T1 - T6 Ga	T6	-40 ... +45 °C	T_M (Mediumstemperatur) + Eigenerwärmung (15 K)
	T5	-40 ... +60 °C	
II 1/2 G Ex ia IIC T1 - T6 Ga/Gb	T4	-40 ... +85 °C	Besondere Bedingungen für die sichere Anwendung berücksichtigen (siehe Kapitel 10.1.1 „Besondere Bedingungen für die Verwendung (X-Conditions)“).
	T3	-40 ... +85 °C	
II 2 G Ex ia IIC T1 - T6 Gb	T2	-40 ... +85 °C	
	T1	-40 ... +85 °C	

Für Anwendungen, die Geräte der Gerätekategorie II (explosionsfähige Staubatmosphären) erfordern, gelten folgende Oberflächentemperaturen und Umgebungstemperaturbereiche:

Tabelle 4

Explosionsgefährdete Staubatmosphäre	Leistung P_i	Umgebungstemperaturbereich (T_a)	Max. Oberflächentemperatur (T_{max}) an der Fühler- oder Schutzrohrspitze
II 1 D Ex ia IIIC T135 °C Da	750 mW	-40 ... +40 °C	T_M (Mediumstemperatur) + Eigenerwärmung (15 K)
	650 mW	-40 ... +70 °C	
II 1/2 D Ex ia IIIC T135 °C Da Db	550 mW	-40 ... +85 °C	Besondere Bedingungen für die sichere Anwendung berücksichtigen (siehe Kapitel 10.1.1 „Besondere Bedingungen für die Verwendung (X-Conditions)“).


10. Hinweise zu Montage und Betrieb im Ex-Bereich

Für Anwendungen, die EPL Gb oder Db erfordern, können die mit „ia“ gekennzeichneten Geräte auch in Messstromkreisen des Typs „ib“ mit den gleichen Anschlussparametern eingesetzt werden!

DE

Somit ist der gesamte Messstromkreis (inklusive dem Sensorkreis) ein „ib“-Stromkreis. Geräte, die in Versorgungsstromkreisen vom Typ „ib“ betrieben wurden, dürfen nicht in Versorgungsstromkreisen vom Typ „ia“ wiederverwendet werden.


10.2 Übersicht der Temperaturzonen



10. Hinweise zu Montage und Betrieb im Ex-Bereich

10.3 Montagebeispiele im explosionsgefährdeten Bereich

DE



11. Berechnungsbeispiele für die Eigenerwärmung an der Schutzrohrspitze

DE

11.1 Beispieldurchrechnung

Einsatz an der Trennwand zur Zone 0

Gesucht wird die maximale mögliche Temperatur T_{\max} an der Schutzrohrspitze Ø 6 mm mit Transmitter.

T_{\max} ergibt sich aus der Addition der Mediumstemperatur sowie der Eigenerwärmung. Die Eigenerwärmung hängt ab von der zugeführten Leistung P_0 sowie dem Wärmewiderstand R_{th} und beträgt 15 K.

Beispiel

Durchmesser: 6 mm

Mediumstemperatur: $T_M = 150 \text{ }^{\circ}\text{C}$

Temperaturklasse T3 (200 °C) darf nicht überschritten werden

Eigenerwärmung: 15 K

$T_{\max} = T_M + \text{Eigenerwärmung}: 150 \text{ }^{\circ}\text{C} + 15 \text{ }^{\circ}\text{C} = 165 \text{ }^{\circ}\text{C}$

Als Sicherheitsabstand für baumustergeprüfte Geräte (für T6 bis T3) müssen von den 200 °C noch 5 °C subtrahiert werden, es wären 195 °C zulässig. Somit wird in diesem Fall die Temperaturklasse T3 nicht überschritten.

Zusatzinformation:

Temperaturklasse für T3 = 200 °C

Sicherheitsabstand für baumustergeprüfte Geräte (T6 bis T3)¹⁾ = 5 K

Sicherheitsabstand für baumustergeprüfte Geräte (T2 bis T1)¹⁾ = 10 K

1) IEC/EN 60079-0: 2012 Abs. 26.5.1

12. Wartung und Reinigung

12.1 Wartung

Die hier beschriebenen Widerstandsthermometer sind wartungsfrei und enthalten keinerlei Bauteile, welche repariert oder ausgetauscht werden könnten.

DE

12.2 Reinigung



VORSICHT!

- Vor der Reinigung des Gerätes elektrische Anschlüsse trennen.
- Das Gerät mit einem feuchten Tuch reinigen. Dies gilt insbesondere für Thermometer mit Gehäusen aus Kunststoff und Kabelfühler mit kunststoffisolierter Anschlussleitung, um die Gefahr von elektrostatischen Aufladungen zu vermeiden.
- Elektrische Anschlüsse nicht mit Feuchtigkeit in Berührung bringen.
- Ausgebautes Gerät vor der Rücksendung spülen bzw. säubern, um Personen und Umwelt vor Gefährdung durch anhaftende Messstoffreste zu schützen.
- Messstoffreste in ausgebauten Geräten können zur Gefährdung von Personen, Umwelt und Einrichtung führen. Ausreichende Vorsichtsmaßnahmen ergreifen.



Hinweise zur Rücksendung des Gerätes siehe Kapitel 14.2 "Rücksendung".

13. Störungen

DE

13. Störungen

Störungen	Ursachen	Maßnahmen
Kein Signal/ Leitungsbruch	Zu hohe mechanische Belastung oder Über-temperatur	Ersatz des Fühlers durch eine geeignete Ausführung
Fehlerhafte Messwerte	Sensordrift durch Über-temperatur	Ersatz des Fühlers durch eine geeignete Ausführung
	Sensordrift durch chemischen Angriff	Medium analysieren
Fehlerhafte Mess- werte (zu gering)	Feuchtigkeitseintritt am Kabel	Geeigneten IP-Schutz verwenden
Fehlerhafte Messwerte und zu lange Ansprech- zeiten	Falsche Einbaugeometrie, z. B. zu geringe Einbautiefe oder zu hohe Wärmeableitung	Der temperaturempfindliche Bereich des Sensors muss innerhalb des Mediums liegen, Oberflächenmessungen müssen isoliert sein
	Ablagerungen auf dem Schutzrohr	Ablagerungen entfernen
Zeitweise oder sporadische Unterbrechungen des Messwertsig- nals	Leitungsbruch im Anschlusskabel oder Wackelkontakt durch mechanische Überbelastung	Ersatz des Fühlers oder dickerer Leitungsquerschnitt
Korrosion	Zusammensetzung des Mediums nicht wie angenommen oder geändert	Medium analysieren
Signal gestört	Einstreuung durch elektrische Felder oder Erdschleifen	Verwendung von geschirmten Anschlussleitungen, Erhöhung des Abstandes zu Motoren und leistungsführenden Leitungen
	Erdschleifen	Beseitigung von Potentialen, Verwendung von galvanisch getrennten Speisetrennern oder Transmittern



VORSICHT!

Können Störungen mit Hilfe der oben aufgeführten Maßnahmen nicht beseitigt werden, ist das Gerät unverzüglich außer Betrieb zu setzen, sicherzustellen, dass kein Signal mehr anliegt und gegen versehentliche Inbetriebnahme zu schützen. In diesem Falle Kontakt mit dem Hersteller aufnehmen. Bei notwendiger Rücksendung die Hinweise siehe Kapitel 14.2 "Rücksendung" beachten.

DE

14. Demontage, Rücksendung und Entsorgung



WARNUNG!

Messstoffreste in ausgebauten Geräten können zur Gefährdung von Personen, Umwelt und Einrichtung führen.
Ausreichende Vorsichtsmaßnahmen ergreifen.

14.1 Demontage



WARNUNG!

Verbrennungsgefahr!

Vor dem Ausbau das Gerät ausreichend abkühlen lassen!
Beim Ausbau besteht Gefahr durch austretende, gefährlich heiße Messstoffe.

Widerstandsthermometer nur im drucklosen Zustand demontieren!

14.2 Rücksendung



WARNUNG!

Beim Versand des Gerätes unbedingt beachten:

Alle an WIKA gelieferten Geräte müssen frei von Gefahrstoffen (Säuren, Laugen, Lösungen, etc.) sein.

Zur Rücksendung des Gerätes die Originalverpackung oder eine geeignete Transportverpackung verwenden.

14. Demontage, Rücksendung und Entsorgung

Um Schäden zu vermeiden:

1. Das Gerät in eine antistatische Plastikfolie einhüllen.
2. Das Gerät mit dem Dämmmaterial in der Verpackung platzieren.
Zu allen Seiten der Transportverpackung gleichmäßig dämmen.
3. Wenn möglich einen Beutel mit Trocknungsmittel der Verpackung beifügen.
4. Sendung als Transport eines hochempfindlichen Messgerätes kennzeichnen.

DE



Hinweise zur Rücksendung befinden sich in der Rubrik „Service“ auf unserer lokalen Internetseite.

14.3 Entsorgung

Durch falsche Entsorgung können Gefahren für die Umwelt entstehen. Gerätekomponenten und Verpackungsmaterialien entsprechend den landesspezifischen Abfallbehandlungs- und Entsorgungsvorschriften umweltgerecht entsorgen.

WIKA subsidiaries worldwide can be found online at www.wika.com.
WIKA-Niederlassungen weltweit finden Sie online unter www.wika.de.



WIKA Alexander Wiegand SE & Co. KG

Alexander-Wiegand-Strasse 30

63911 Klingenberg • Germany

Tel. +49 9372 132-0

Fax +49 9372 132-406

info@wika.de

www.wika.de