

SUPPLEMENT TO OPERATING INSTRUCTIONS

Additional Information for S700 Series

Ergänzende Informationen zur Serie S700

DE

EN



Document Information

Document ID

Title: Supplement to Operating Instructions
Part No.: 8018633
Version: 1.0
Release: 2015-06

Products concerned

SICK S700 Series
Manual 8009719 (German language)
Manual 8009720 (English language)

Manufacturer

SICK AG
Erwin-Sick-Str. 1 · 79183 Waldkirch · Germany

Legal information

Subject to change without notice.

© SICK AG. All rights reserved.

1 Deutsch

1.1 Über dieses Dokument

- Diese Zusatz-Betriebsanleitung ist Bestandteil des Lieferumfangs und enthält ergänzende Informationen zur Betriebsanleitung 8009719 „Betriebsanleitung Bau-reihe S700“



WICHTIG:

Dieses Handbuch ist nur gültig im Zusammenhang mit der Betriebsanleitung 8009719 des S700.

1.2 Verantwortung des Anwenders

- ▶ Nehmen Sie Ihr Gerät nur in Betrieb, wenn Sie diese Zusatz-Betriebsanleitung gelesen haben.
- ▶ Beachten Sie alle Sicherheitshinweise und zusätzlichen Informationen.
- ▶ Wenn etwas unklar ist: Kontaktieren Sie bitte den SICK-Kundendienst.

Aufbewahren der Dokumente

- Diese Zusatz-Betriebsanleitung zusammen mit der Betriebsanleitung zum Nachschlagen bereit halten.
- An neue Besitzer weitergeben.

DE

1.3

Kapitel 3.6 neue Version

Spülgas-Anschlüsse (Option)

Gilt nur für Geräte mit Gasanschlüssen PURGE IN /PURGE OUT

S710/S711

- Bei Bedarf: Über den Anschluss PURGE IN Spülgas in das Gehäuse leiten (Betriebsbedingungen nach Wahl des Anwenders).

S715 ohne Überdruckkapselung

- Bei Bedarf: Über die Anschlüsse PURGE IN und PURGE OUT Spülgas durch das Gehäuse leiten.



- Das Gehäuse des S715 ist „schwadendicht“ gemäß EN 60079. (Kriterium: Die Zeit, in der ein Unterdruck im geschlossenen Gehäuse von 3 mbar auf 1,5 mbar steigt, beträgt mehr als 90 Sekunden.)
- Wenn der S715 in einem explosionsgefährdeten Bereich (Zone 2) eingesetzt wird, muss es möglich sein, die Spülgas-Anschlüsse bei der Dichtheitsprüfung des Gehäuses zu öffnen bzw. zu verschließen (→ S. 216, § 16.2).

DE

1.4

Kapitel 16.2.1 neue Version

Prozedur der Dichtheitsprüfung

1 Gasanschluss vorbereiten:

Bei Geräten ohne Spülgas-Anschlüsse	Bei Geräten mit Spülgas-Anschläussen
<p>1 Die Verschraubung an der linken Gehäuseseite lösen und den Verschlusszapfen herausnehmen (→ Seite 5).</p> <p>2 Die Schlaucholive (im Lieferumfang) anstelle des Verschlusszapfens einbauen. Verschraubung gasdicht anziehen.</p>	<p>1 Einen der beiden Spülgas-Anschlüsse gasdicht verschließen (z.B. mit einem Absperrventil).</p> <p>2 Den zweiten Spülgas-Anschluss so vorbereiten, dass ein Gas eingeleitet werden kann, aber kein Gas entweichen kann (falls keine entsprechenden Installationen vorhanden sind, die Gasleitung vom Spülgas-Anschluss lösen und z.B. durch einen Schlauchanschluss ersetzen).</p>

- 2 An den Schlauchanschluss ein Manometer anschließen (Messbereich 0 ... 300 Pa erfassend) sowie eine Einrichtung, mit der im S715 ein Unterdruck von 300 Pa (3 mbar) erzeugt werden kann (z.B. eine Pumpe).
- 3 Im S715 ein Unterdruck von 300 Pa (3 mbar) erzeugen und verschließen. Den Druck am Manometer ablesen.



Eine größere Druckdifferenz kann das Gehäuse beschädigen.

- Keine größeren Druck als den angegebenen Druck verwenden.



Obwohl die Druckdifferenz klein ist, kann es einige Minuten dauern, bis die nötige Druckdifferenz aufgebaut ist.



4 Nach 90 Sekunden das Manometer erneut ablesen:

Druck ist um höchstens 150 Pa gestiegen	Druck ist um mehr als 150 Pa gestiegen
<p>Der Test ist bestanden.</p> <p>1 Die Testinstallationen entfernen.</p> <p>2 Abwarten, bis der Druck vollständig aus dem Gehäuse entwichen ist.</p> <p>3 Den Verschlusszapfen wieder gasdicht installieren.</p> <p>Danach darf der S715 in Betrieb genommen werden.</p>	<p>Der Test ist nicht bestanden.</p> <p>1 Abdichtung des Gehäuses prüfen (Gehäusedichtungen, Kableinführungen, Verschlusschrauben).</p> <p>2 Danach den Test erneut durchführen.</p>

Bild 1

Dichtheitsprüfung in Zone 2 für S715 ohne Überdruckkapselung

DE



DE

2 English

2.1 About this document

- These Supplementary Operating Instructions are part of the scope of delivery and contain supplementary information for the Operating Instructions of Series S700, manual 8009720.



NOTICE:

This Manual is only valid in connection with the Operating Instructions 8009720 of the S700.

2.2 Responsibility of user

- ▶ Only put your equipment into operation after reading these Supplementary Operating Instructions.
- ▶ Observe all safety information and additional information.
- ▶ Please contact SICK Customer Service should anything be unclear.

Retention of documents

These Supplementary Operating Instructions together with the Operating Instructions

- Must be kept available for reference.
- Must be conveyed to new owners.

EN

2.3

Chapter 3.6 new version

Purge gas connections (option)

Only applies to analyzers with PURGE_IN/PURGE_OUT gas connections

S710/S711

- If required: Feed-in purge gas via the PURGE IN fitting (according to your own requirements).

S715 without enclosure pressurization

- If required: Connect a purge gas supply to the PURGE IN and PURGE OUT fittings.



- The S715 enclosure is »vapor-tight« according to the European standard EN 60079. (Criterion: The time for which it takes for an underpressure of 3 mbar to rise to 1.5 mbar in an closed instrument is greater than 90 seconds.)
- If the S715 is used in an explosion-hazardous location (Zone 2), it is required the use the purge gas inlet and seal the purge gas outlet when performing the leak rate test (→ page 216, §16.2).

2.4

Chapter 16.2.1 new version

EN

Leak test procedure

- 1 Prepare a gas connection:

For analyzers without purge gas connections	For analyzers with purge gas connections
<ol style="list-style-type: none"> 1 Loosen the fitting on the left side of the enclosure and remove the closing plug (→ p. 9). 2 Replace the plug with a hose connector (supplied with the analyzer) and make the fitting gas-tight again. 	<ol style="list-style-type: none"> 1 Block or seal one of the purge gas connections, for example by closing an valve in the external purge gas line. 2 Prepare the other purge gas connection in order to allow the introduction of gas, however in such a way that the connection can be closed. (If no special equipment has been installed for this purpose, disconnect the external purge gas line from the connector and install a hose connector instead.)

- 2 Connect a manometer to the hose connection (measuring range should cover 0 ... 300 Pa) and a device which can be used to introduce a gas under-pressure into the S715 (for example, a gas pump).
- 3 Now produce an under-pressure inside the S715 of 300 Pa (3 mbar) against ambient pressure. Then block the gas line and read the manometer.



A higher pressure difference can damage the enclosure.
 ► Do not apply a higher pressure than specified.




Although the pressure is rather low, it may take some minutes to establish the required pressure difference.

4 After 90 seconds, read the manometer again:

If the pressure has increased for no more than 150 Pa:	If the pressure has increased for <i>more</i> than 150 Pa:
<p>Test is passed.</p> <ol style="list-style-type: none"> 1 Remove the test installations. 2 Wait until the pressure has fully removed from the enclosure. 3 Re-install the closing plug <p>When all this has been completed, the S715 may be started-up again.</p>	<p>Test has failed.</p> <ol style="list-style-type: none"> 1 Check the sealing of the enclosure (sealings, cable glands, closing caps). 2 Then perform the test again.

Figure 2

Leak rate test procedure in Zone 2 for S715 without enclosure pressurization



Australia Phone +61 3 9457 0600 1800 33 48 02 – tollfree E-Mail sales@sick.com.au	Norge Phone +47 67 81 50 00 E-Mail sick@sick.no
Belgium/Luxembourg Phone +32 (0)2 466 55 66 E-Mail info@sick.be	Österreich Phone +43 (0)22 36 62 28 8-0 E-Mail office@sick.at
Brasil Phone +55 11 3215-4900 E-Mail marketing@sick.com.br	Polka Phone +48 22 837 40 50 E-Mail info@sick.pl
Canada Phone +1 905 771 14 44 E-Mail information@sick.com	România Phone +40 356 171 120 E-Mail office@sick.ro
Česká republika Phone +420 2 57 91 18 50 E-Mail sick@sick.cz	Russia Phone +7-495-775-05-30 E-Mail info@sick.ru
China Phone +86 4000 121 000 E-Mail info.china@sick.net.cn Phone +852-2153 6300 E-Mail gk@sick.com.hk	Schweiz Phone +41 41 619 29 39 E-Mail contact@sick.ch
Danmark Phone +45 45 82 64 00 E-Mail sick@sick.dk	Singapore Phone +65 6744 3732 E-Mail sales.gsg@sick.com
Deutschland Phone +49 211 5301-301 E-Mail info@sick.de	Slovenija Phone +386 (0)1-47 69 990 E-Mail office@sick.si
España Phone +34 93 480 31 00 E-Mail info@sick.es	South Africa Phone +27 11 472 3733 E-Mail info@sickautomation.co.za
France Phone +33 1 64 62 35 00 E-Mail info@sick.fr	South Korea Phone +82 2 786 6321/4 E-Mail info@sickkorea.net
Great Britain Phone +44 (0)1727 831121 E-Mail info@sick.co.uk	Suomi Phone +358-9-25 15 800 E-Mail sick@sick.fi
India Phone +91-22-4033 8333 E-Mail info@sick-india.com	Sverige Phone +46 10 110 10 00 E-Mail info@sick.se
Israel Phone +972-4-6881000 E-Mail info@sick-sensors.com	Taiwan Phone +886-2-2375-6288 E-Mail sales@sick.com.tw
Italia Phone +39 02 27 43 41 E-Mail info@sick.it	Türkiye Phone +90 (216) 528 50 00 E-Mail info@sick.com.tr
Japan Phone +81 (0)3 5309 2112 E-Mail support@sick.jp	United Arab Emirates Phone +971 (0) 4 8865 878 E-Mail info@sick.ae
Magyarország Phone +36 1 371 2680 E-Mail office@sick.hu	USA/México Phone +1(952) 941-6780 1 800 325-7425 – tollfree E-Mail info@sickusa.com
Nederland Phone +31 (0)30 229 25 44 E-Mail info@sick.nl	More representatives and agencies at www.sick.com

SICK

Sensor Intelligence.